



## U. S. Chemical Safety and Hazard Investigation Board RECOMMENDATION STATUS CHANGE SUMMARY

<b>Report:</b>	Wacker Polysilicon Chemical Release
<b>Recommendation Number:</b>	2021-01-I-TN-R9
<b>Date Issued:</b>	June 8, 2023
<b>Recipient:</b>	International Code Council (ICC)
<b>New Status:</b>	Open – Awaiting Response or Evaluation/Approval of Response
<b>Date of Status Change:</b>	Not Applicable – Initial Status

### Recommendation Text:

*Amend the International Building Code (IBC) to address conditions that may require multiple means of egress from elevated equipment platforms used for accessing equipment containing materials that pose physical and health hazards, such as the one used at Wacker in this incident. Specify the minimum number of egress points to increase the likelihood of worker escape in the event of a hazardous material release.*

### Board Status Change Decision:

#### A. Rationale for Recommendation

On November 13, 2020, a graphite heat exchanger cracked during maintenance activities, releasing anhydrous hydrogen chloride at the Wacker Polysilicon facility in Charleston, Tennessee. The incident occurred on the fifth floor of an equipment access structure when a contractor applied excessive torque to flange bolts on the heat exchanger's discharge pipe.

Seven workers from two contracted companies were in close proximity to the release. The location of the release prevented the workers from accessing the platform's single means of egress. While attempting to escape by climbing down piping on the side of the structure, three of the workers fell to the ground, fatally injuring one and seriously injuring the other two. The other four workers remained in place until the release ended. One of these four workers sustained chemical burns from the release due to a rip in their personal protective equipment (PPE). The remaining three workers were uninjured.

The U.S. Chemical Safety and Hazard Investigation Board (CSB) investigated the incident and found several safety issues including ineffective written procedures, control of hazardous energy, and management of hazards during simultaneous operations (SIMOPs), as well as an insufficient means of egress from the platform. As a result of these findings, the CSB issued one recommendation to the International Code Council (ICC). This status change summary addresses **CSB Recommendation No. 2021-01-I-TN-R9**.