



U. S. Chemical Safety Board

SONAT INVESTIGATION



Presentation Of Findings to the Board

Public Board Meeting
September 15, 2000



Sonat Investigation

INTRODUCTION

- March 4, 1998, near Pitkin, LA
- Startup of Oil / Gas Separation Equipment
- Natural Gas Purge of Vessels and Pipeline
- Oil / Gas Separator Overpressurized
- Catastrophic Vessel Failure
- Four Operators Killed


Aerial View of Sonat's Temple 22-1 Common Point Separation Facility




Aerial View of Sonat's Temple 22-1 Common Point Separation Facility



Block Flow Diagram of the Separation Process



Third Stage Separator Schematic





Sonat Investigation

TERMINOLOGY

Sonat referred to the failed vessel as a
"Vapor Recovery Tower" or storage tank

SB determined that the vessel actually fit
the definition of an oil and gas separator



Sonat Investigation

TERMINOLOGY

separator had a single inlet line for oil/gas mixture but two separate outlet lines

separator was not designed for permanent oil storage

separator was positioned upstream of the storage tanks in series with the 1st and 2nd



Sonat Investigation

INCIDENT TIMELINE



EARLY AFTERNOON

- Separation vessels purged using well fluids

LATE AFTERNOON

- Valves realigned to purge pipeline, through a bypass line and two water storage tanks, out a tank roof hatch to the atmosphere

ended Valve Positions after the Final Alignment





Sonat Investigation

INCIDENT TIMELINE

- 10 PM** - Pipeline purge initiated using well fluids
- 15 PM** - Supervisor initiated monitoring oxygen content in pipeline near header
- 35 PM** - Pressure into pipeline increased for the third and final time



Sonat Investigation

INCIDENT TIMELINE

00 PM - Pressure reading downstream of well and flow control valve was recorded as 800 psig

10 PM - Final oxygen reading taken indicating purge nearly completed



Sonat Investigation

INCIDENT TIMELINE

- 15 PM** - Bulk Train third stage separator failed, natural gas released and ignited producing large fireball
- Four operators killed instantly
 - Damaged tanks and piping leak oil and gas which ignites

Damaged Vehicles and Storage Tanks








Sonat Investigation

INCIDENT TIMELINE

1:05 PM - Sonat supervisors and LA State Police investigated incident site and discovered two bypass valves for the failed third stage separator in the closed position, which should have been open

Comparison of Valve Alignments as “Planned” and as “Found”





Sonat Investigation

KEY FINDINGS

1:

The third stage separator that failed could not be isolated from an adjacent bypass line, because there was no inlet valve. Two valves on the bypass line and all other outlet valves were closed allowing high-pressure purge gases to overpressurize and rupture the separator.



Sonat Investigation

KEY FINDINGS

2:

The third-stage separator was only rated for atmospheric pressure service (0 psig).

The purge gas stream to which the separator was exposed to had a pressure potentially as high as 800 psig.



Sonat Investigation

KEY FINDINGS

3:

The third stage separator was not equipped with any pressure-relief devices as specified by API Specification 12J which states “all separators, regardless of size or pressure, shall be provided with pressure protective devices”. The vessel that failed falls within the scope of this specification



Sonat Investigation

KEY FINDINGS

4:

Why the bypass valves were closed or when they were closed could not be conclusively established



Sonat Investigation

KEY FINDINGS

5:

Management did not perform effective engineering design reviews or hazard analyses prior to or during the construction of the facility.



Sonat Investigation

KEY FINDINGS

6:

Workers at the facility were not provided with written operating procedures addressing the proper alignment of valves for purging operations.



Sonat Investigation

KEY FINDINGS

7:

Sonata operated similar third-stage separators that lacked pressure-relief systems at other oil and gas production facilities for over a year prior to the incident.

U. S. Chemical Safety Board

SONAT INVESTIGATION



resentation Of Findings to the Board

Public Board Meeting

