



Anamet, inc *Materials Engineering & Laboratory Testing*

26102 EDEN LANDING ROAD, SUITE 3 • HAYWARD, CALIFORNIA 94545 • (510) 887-8811 • FAX (510) 887-8427

METALLURGICAL EVALUATION OF WILLIAMS OLEFINS RUPTURED REBOILER EA-425B

Prepared for: The U.S. Chemical Safety and Hazard Investigation Board (CSB)

Report No. 5004.9095 B

September 2016



This report shall not be reproduced, except in full, without the written approval of Anamet.



1.0 INTRODUCTION

This report summarizes the laboratory metallurgical examination and testing of shell and process piping sections from ruptured reboiler EA-425B involved in the June 13, 2013 fire and explosion at the Williams Olefins Plant in Geismar, Louisiana. The work was performed at Anamet Inc. from December 9 to December 20, 2013. Personnel from Engineering Systems, Inc. (ESI), representing Williams Olefins, participated in the evaluation. The contents of this report are the work product of Anamet, Inc., under contract to the U.S. Chemical Safety Board (CSB).

Details of the subject reboiler construction and sequence of events prior to the reboiler rupture were reported by the CSB. Reboiler EA-425B was a six-pass, straight tube, divided flow shell design constructed in 1967. A drawing of the reboiler is shown in Appendix A. As indicated on the Form U-1 shown in Appendix B, the 11/16-inch thick shell material specification was SA-212-B-FBQ which is equivalent to ASTM A212 Grade B firebox quality. The A212 standard was withdrawn in 1967. The maximum allowable working pressure of the shell side was 300-psig, at a maximum temperature of 200 °F. Process fluid on the shell side was approximately 95% propane with the balance composed mostly of propylene and C4 hydrocarbons, which entered the reboiler as liquid and exited as liquid and vapor. The MAWP of the tube side was 157-psig at a maximum temperature of 220 °F.

Preceding the incident, the subject reboiler EA-425B was off-line and blocked in, all process stream and quench water valves closed. The parallel reboiler EA-425A was on-line. The system had been in this configuration for 16 months. Operators adjusted quench water flow in the system to compensate for fouling in EA-425A by opening the quench water inlet and outlet valves of the subject reboiler EA-425B, while the process inlet and outlet valves remained closed. Quench water entered EA-425B at approximately 185 °F. A few minutes after opening the quench water valves, the shell of reboiler EA-425B ruptured catastrophically.

The purpose of this evaluation was to determine the physical origin and metallurgical mechanism of shell rupture.

Sections of the ruptured reboiler EA-425B and a coupon cut from the parallel reboiler EA-425A were evaluated by the following laboratory procedures:

- 1) Visual and macroscopic examination
- 2) Scanning electron microscopy
- 3) Metallography
- 4) Chemical analysis
- 5) Mechanical testing



1.1 Summary of Findings

Based on the results of this evaluation, fracture of reboiler EA-425B likely first initiated in the north end outlet pad longitudinal seam weld. No evidence was found of cracks pre-existing the rupture event. The chemical composition and tensile properties of the ruptured shell EA-425B and the parallel EA-425A reboiler shell met the requirements for ASTM A212 Grade B Firebox steel. Charpy V-notch impact toughness testing indicated that the EA-425A shell met the requirements ASME Section VIII, Figure UG-84.1, at 50 °F and above.

2.0 EVALUATION¹

2.1 Visual Examination

2.1.1 Onsite visual examination

Photographs of the ruptured reboiler taken at the incident site are shown in Figure 1 and Figure 2. After the incident site was stabilized and all identifiable EA-425B reboiler artifacts were cataloged by ESI under contract to Williams Olefins, the artifacts were moved to a tented area of the refinery. Prior to the onsite visual examination on September 17 and 18, 2013, fracture surfaces had been coated with petroleum jelly according to an agreed upon artifact preservation protocol. The petroleum jelly did not interfere with the objective of the onsite visual exam, which was to identify sections of the shell for detailed laboratory evaluation. Photographs of the tube bundle and ruptured shell in the tented area are shown in Figure 3 through Figure 7. Visual examination of the artifacts was performed by Anamet and others on September 17 and 18, 2013.

The tube bundle was deformed about the vertical center plane as shown in Figure 2. Fractured tube ends photographed from alongside the bundle are shown in Figure 4. Necked ends indicated ductile overload fracture. Both the deformation of the bundle and the necked tube ends were consistent with post shell rupture damage.

The ruptured section of shell shown in Figure 5 was formed from the reboiler by three major fracture paths, summarized graphically in Figure 6. Longitudinal fracture propagated between the north end tube sheet and approximately three-quarters of the distance to the south end tube sheet, bisecting the north outlet. Both of the mating longitudinal fracture surfaces were on this shell section. Longitudinal fracture propagated through the shell well away from longitudinal shell seam welds. Circumferential fracture propagated at the south end of the section, and the mating fracture surface was on the shell section still connected to the south end tube sheet. South end circumferential fracture propagated well away from the nearest circumferential seam weld. Circumferential fracture propagated along the shell to tube sheet weld at the north end; the mating surface was on the north end tube sheet.

Chevron marks, indicating fracture directions, were present on the majority of the longitudinal fracture surfaces. Macroscopically brittle fracture morphology with small shear lips predominated, indicating mode I loading shown in Appendix C. Four longitudinal fracture initiation sites were identified and arbitrarily labeled 1 through 4, beginning at the north end, as

¹ The magnifications of the optical and scanning electron micrographs in this report are approximate and should not be used as a basis for dimensional analyses unless otherwise indicated.



indicated in Figure 7b. Initiation site 1 was located in the shell, near the inside surface at the north side of the north outlet. Chevron marks indicated a fracture path from initiation site 1 to the north end tube sheet. Fracture initiation site 2 was located in the shell just below the south edge of the north outlet pad. Chevron marks indicated fracture from site 2 toward the north through the outlet, and toward the south for approximately 40-inches from the centerline of the north outlet. Fracture initiation site 3 was located on the outside surface of the shell, approximately 44-inches from the centerline of the north outlet. Chevron marks indicated fracture propagated from site 3 to the north for approximately 4-inches, where the fracture met the south bound fracture front from site 2, and propagated to the south toward site 4. Initiation site 4 was located on the inside surface of the shell, approximately 104-inches from the center of the north outlet. Shallow arc gouges were present on the shell inside surface at initiation site 4. The pattern of chevron marks indicates fracture initiation at site 4 occurred late in the shell rupture event.

A shell fragment between initiation site 3 and 4 had detached from the main section of ruptured shell, tagged by ESI as number 117 and shown in Figure 8. It was reported that the fragment had been found in a tank yard, a considerable distance from the reboiler location. On the east side of the main ruptured section, fracture propagated directly from site 3 to site 4. On the west side of the ruptured section, fracture propagated from site 4 north to approximately 76-inches from the centerline of the north outlet, where the fracture front intersected the surface created by the southbound propagation from site 3.

Chevron marks on the south end circumferential fracture surfaces indicated that the longitudinal fracture bifurcated at the point indicated in Figure 3b, and then propagated around the shell along two paths. The bifurcation occurred in a region of shell free of gouges, thickness changes, welds, or other discontinuities. The two circumferential crack paths joined in a region near the underside of the reboiler. There was a significant proportion of slant morphology indicative of mode III loading, shown in Appendix C.

North end circumferential fracture propagated predominantly along the shell to tube sheet weld, with much of the weld metal remained adhered to the tube sheet. Clear chevron marks were present only in regions where circumferential fracture propagated for a short distance through shell base metal.

Chevron marks on the longitudinal fracture surfaces of the north outlet, shown in Figure 1 and Figure 9, indicated fracture propagated from the shell into the outlet wall under mode I loading. Circumferential fracture of the outlet propagated predominantly in the outlet base metal through the toe of the circumferential weld between the pad and the outlet wall. Regions of slant morphology on the outlet circumferential fracture surfaces indicated a mode III loading component.

No unusual or extensive corrosion was detected on the shell or ruptured outlet. Shell thickness measurements made with dial calipers at several points along the fracture surface ranged from 0.70-inch to 0.68-inch. These measurements included tenacious scale on both surfaces of the shell.

Following the visual examination in the tented area, all parties agreed to a protocol for sectioning the ruptured reboiler shell according to the layout shown in Figure 10 and Figure 11. The

sectioning protocol also included cutting the process piping to isolate the outlet pipe fractures. After flame cutting, the sections were sealed into wood crates by ESI.

At a later date, coupons were cut from the parallel reboiler EA-425A and shipped to Anamet. It was reported that the samples were cut from the side of EA-425A farthest from the ruptured reboiler, which should have been least affected by the rupture and fire. These coupons were intended primarily for mechanical testing to address questions about the effects of rupture on the mechanical properties of reboiler EA-425B. Chemical analysis and metallography were also performed on specimens from the EA-425A shell coupons. The coupons are shown in Figure 12 and Figure 13.

2.1.2 Laboratory Visual Examination

The crated sections were received by Anamet in Hayward, CA on November 18, 2013. The crates were opened two days later, and the general condition of the contents was examined by a representative of ESI who was present at the time the crates had been sealed at the Williams refinery. Table 1 lists the samples received. On December 9, 2013, with representatives from ESI present, the crates were unloaded and placed on stands or carts in the laboratory. Shell sections set up in the laboratory are shown in Figure 14 through Figure 18. Representatives of ESI participated in all aspects of the following laboratory evaluation. Specimen identification numbers assigned by ESI were maintained throughout the evaluation. When sections were subdivided, ESI assigned numbers that were appended to the parent identification number. The laboratory work concluded with re-crating reboiler EA-425B sections, subdivided sections, and test specimens on December 20, 2013. One subdivided sample, 164-1.03, was retained by Anamet for additional mechanical testing.

Fracture surfaces were cleaned with hexane applied from laboratory squeeze bottles, soft bristle chip brushes, and dried with compressed air. Visual examination and photographic documentation of the fracture surfaces was performed in a well lighted room. Three dimensional laser scanning of the surfaces was performed by ESI, the results of which are not included in this report. Examination of the cleaned fracture surfaces revealed no additional fracture initiation sites or fracture directions different from those identified during the onsite examination.

Photographs of fracture initiation site 1 are shown in Figure 19 and after sectioning and additional cleaning, in Figure 20. Fracture initiated in close proximity to weld metal on the inside shell surface. The weld was revealed by light grinding and etching with 2% nital. As shown by the dashed line in Figure 20b, the weld metal was outside of the shell to outlet weld joint, probably within a repair or surface smoothing weld. Secondary cracks parallel to the fracture were present, as shown in Figure 21. Fracture propagated from the initiation site through the shell and outlet pad into the shell to tube sheet weld, and into the outlet. No evidence of an initiation crack that pre-existed the rupture event was detected.

Fracture initiation site 2 is shown in Figure 22 and, after sectioning and further cleaning in Figure 23. Fracture initiated under the shell to outlet pad fillet weld. Fracture propagated to the north through the shell and outlet pad into the outlet and south through the shell toward initiation site 3. The south bound fracture front from initiation site 2 met the north bound front from initiation site 3 in a shell circumferential seam weld, as shown in Figure 24. No evidence of an initiation crack that pre-existed the rupture event was detected. The outlet pad partial penetration

seam weld was visible after cleaning. A transverse crack in the shell that intersected the toe of the shell to outlet pad fillet weld in section 164-1 occurred post rupture, as evidenced by the mode III loading displacement of the shell, indicated in Figure 22b.

The outlet pad had been fabricated from halves that were joined by a partial penetration longitudinal seam weld. This seam weld was aligned with the shell axis at the top center position, and was co-planar with the longitudinal fracture path, which propagated through the outlet pad seam weld.

Photographs of fracture initiation site 3 are shown in Figure 25 and, after sectioning and further cleaning, in Figure 26. Fracture initiated on the outside surface of the shell in a surface weld revealed by grinding and etching with 2% nital, as shown in Figure 26b. The weld was consistent with what would remain after a handling lug or fixture was removed during construction. Based on optical and scanning electron microscopy of the initiation site, no crack was present prior to the rupture event. Fracture propagated a short distance north to a circumferential seam weld, where it intersected the south bound front from initiation site 2, and south to initiation site 4. Part of the fracture surface formed during the south bound propagation was on section 117, as indicated in Figure 27b.

Fracture initiated at site 4 from arc gouges on the inside surface of the shell, as shown in Figure 28 and Figure 29a. Part of the fracture path from site 4 traveled north, formed one side of section 117, and intersected the surface created by fracture that propagated south bound from site 3. Fracture also propagated from site 4 to the south. Section 164-3 is shown in Figure 29b to help demonstrate the relationship of the surfaces shown in Figure 28, and how section 117 fit with section 164-3.

Photographs of the shell circumferential fracture surface at the north end tube sheet are shown in Figure 30 and Figure 31. A section through the shell to tube sheet fracture prepared for metallography is shown in Figure 32. The predominant fracture path was through the weld heat affected zone in the tube sheet. Clear chevron marks were not present on the resulting fracture surface. However, in one region shown in Figure 31a, the fracture path intersected the shell base metal for a short distance, and chevron marks indicated a fracture direction from the outlet toward the underside of the reboiler. Some evidence of poor weld root fusion to the tube sheet was present. Because none of the evidence indicated tube sheet weld root fusion to be causal to the fracture, detailed evaluation was not conducted in these regions.

A shell fracture path map was constructed by tracing the fracture surfaces of sections 164-1 through 164-4, and 117. The tracings were transferred to a single sheet of paper, shown in Figure 33a. In addition to demonstrating the geometric relationship of section 117 to the fracture surfaces of 164-2 and 164-3, fracture directions from initiation sites 2 through 4 are indicated on the map. Except for a 4-inch section of north bound fracture from site 3 toward site 2, a south bound fracture direction was uninterrupted until it bifurcated at the transition to circumferential fracture near the south outlet. The fracture paths are schematically indicated on a drawing in Figure 33b.

Scanning electron microscopy described in Section 2.2 indicated shell fracture propagated by cleavage. Cleavage fracture is unstable, with a propagation rate likely near the speed of sound. Had fracture first initiated at site 3, it is unlikely that the short north bound crack would have

arrested at the girth weld until the longer southbound crack from site 2 also reached the girth weld. It is much more likely that fracture initiated at site 3 as the south bound crack from site 2 approached the girth weld. Regarding initiation site 4, a crack propagated north from site 4 and intersected the south bound crack path from site 3. Because the south bound crack path from site 3 was longer than the north bound crack path from site 4, initiation at site 2 occurred before initiation at site 4. Based on the physical evidence alone, first fracture could have initiated at site 1 or site 2, and fracture modeling results described in Section 2.6 also indicate first fracture could have initiated from site 1 or site 2.

Ruptured outlet fracture surfaces indicated fracture direction from the outlet pad joint into the outlet, as shown in Figure 34a and Figure 35. Examination of the remainder of the process piping fractures indicated that they resulted from the shell rupture and were not causal to the rupture. For example, the fractured tee connection between the outlet and the fractionator tower piping, shown in Figure 34b, resulted from the energy released by the shell rupture.

2.2 Scanning Electron Microscopy

One surface was sectioned from each fracture initiation site and examined using a scanning electron microscope (SEM). All of the fracture surfaces were covered with rust that had formed before the site was sufficiently stabilized to allow access and application of petroleum jelly. Therefore, each section was cleaned in acetone with ultrasonic agitation, then in 2% Citrinex® at approximately 90 °F with ultrasonic agitation. Times in the Citrinex® solution were limited to 5-minutes or less before the specimen was rinsed with water, dried with compressed air, and examined. Most specimens required only one cleaning cycle before areas of clean metal sufficient to allow SEM examination were exposed. Although Citrinex® is effective at removing rust, prolonged exposure of bare metal to the solution will result in surface attack. Consequently, cleaning cycles were minimized to that necessary to reveal the fracture morphology by SEM examination. Fracture initiation sites 1 and 2 were the most difficult to clean. Had cracks been present in the shell prior to the rupture event, it can be expected that corrosion product on the crack surfaces would have been thicker and more difficult to remove than on the surfaces created during the rupture. Because no features at the fracture origins were found to have scale that was different from the surrounding fracture surface, no evidence of preexisting cracks was found. Various combinations of fracture morphology and surface damage from corrosion and cleaning were observed with SEM.

Fracture initiation site 1, cut from section 164-1, is shown after cleaning in Figure 36. Corroded cleavage morphology was present on the shell fracture surface, as shown in Figure 37 through Figure 39. Fractured weld metal on the inside surface of the shell, indicated in Figure 20, had a fine dimpled morphology that indicated microscopic ductility, shown in Figure 40. Fine dimples were also present on the outlet pad partial penetration seam weld fracture, shown in Figure 41.

The specimen of initiation site 2 sectioned from sample 164-4 and shown in Figure 42 was the most difficult of all the initiation sites to clean. In addition to the rust found on all the other specimens, a dark grey tenacious oxide layer was present over the majority of the surface, indicative of exposure to elevated temperatures during the post-rupture incident fire. However, remnants of cleavage morphology were present in the shell at the fracture initiation site, as shown in Figure 43. Most of the shell fracture surface morphology was similar to that shown in Figure 44 and Figure 45, which indicates post fracture damage consistent with elevated



temperature exposure. Fracture through the shell to pad fillet weld had some dimple morphology indicative of microscopically ductile fracture, as shown in Figure 46, although macroscopically the weld fracture was brittle. The fillet weld fracture morphology shown in Figure 47 suggested a combination of dimples and cleavage with corrosion damage. A fine dimpled morphology of the outlet pad seam weld fracture was consistent with ductile morphology observed on the initiation site 1 specimen of the outlet pad weld.

Initiation site 3, sectioned from sample 164-1, is shown in Figure 49. Fracture initiated from weld metal on the outside surface, as shown in Figure 26b. The fracture morphology of the weld metal was a combination of cleavage and dimples, sometimes described as quasi-cleavage, with light corrosion damage, shown in Figure 50. Cleaning removed the oxide layer on the thumbnail shaped origin as quickly as on the rest of the fracture surface. Therefore, the thumbnail shaped crack was likely created during shell rupture. Cleavage morphology of the shell near initiation site 3 is shown in Figure 51 and Figure 52.

Initiation site 4, sectioned from sample 164-2, is shown in Figure 53. Fracture initiated from two arc gouges on the inside surface of the shell, one of which is shown in Figure 54. The shell fracture morphology was cleavage, as shown in Figure 55 and Figure 56.

2.3 Metallography

Specimens were prepared for metallography to examine the general microstructure of the shell in the circumferential and shell longitudinal orientations from samples 164-4.01 and 164-3.01. Photographs indicating the section orientations and representative micrographs are shown in Figure 57 through Figure 62. Based on the morphology of inclusion stringers, the shell plate longitudinal direction (rolling direction) was circumferential about the shell. Inclusion content was not unusual for this vintage steel, and the fractions of pearlite and ferrite were consistent with ASTM A212 chemical composition.

A section was cut parallel to the shell fracture surface at initiation site 2 and prepared for metallography, as shown in Figure 63. Comparison of the fracture surface and the etched metallographic specimen indicated that fracture initiated in the shell heat affected zone (HAZ), of the shell to outlet pad fillet weld. Widmanstatten and blocky ferrite microstructures with fine distributions of unresolved pearlite typical of multiple pass carbon steel weld metals were present in the fillet weld. Representative micrographs are shown in Figure 64 through Figure 66. The microstructures in the shell HAZ were typical of carbon steel. A Knoop 500-g microhardness survey was performed along the line indicated in Figure 63, and the results are shown in Figure 64. Hardness was fairly uniform between 231 HK and 246 HK from the weld into the unaffected shell, but four readings in the heat affected zone ranged from 252 HK to 267 HK. Converted to Rockwell scales, the readings ranged from 95 to 100 Rockwell B (HRB), with four readings between 20 and 24 Rockwell C (HRC). On the Rockwell scales, hardness greater than 100 HRB is covered by the C scale, which begins at 20 HRC.

Metallographic confirmation of the outlet pad partial penetration seam weld is shown in Figure 70 through Figure 72. The weld and HAZ microstructures of the pad seam weld were similar to those in the pad to shell fillet weld. Both the surface morphology and an HAZ below the root of the seam weld indicated the pad was flame cut during construction. The drawing in Appendix A indicates the jumper pad was made from the same steel specified for the shell, ASTM A212



Grade B. Therefore, similar microstructures compared to the shell and pad fillet weld is consistent.

A surface weld near fracture initiation site 1 and at fracture initiation site 3 were confirmed by macroetch of the surface. Arc gouges at initiation site 4 were identified by macroscopic and microscopic (SEM) morphology. Because no evidence that surface weld cracks existed before the rupture event was found, and because of time constraints, the microstructures of surface welds and arc gouges were not examined.

Metallography was performed on specimens from the EA-425A reboiler shell coupon 1. Micrographs representative of the coupon microstructure structure are shown in Figure 67 and Figure 68.

2.4 Chemical Analysis

Quantitative chemical analysis was performed on specimens from reboiler EA-425B shell samples 164-1.01 and 164-3.01, shown in Figure 57 and Figure 60, respectively. Chemical analysis was also performed on a specimen from the parallel reboiler EA-425A coupon 1. The carbon and sulfur concentrations were determined by LECO combustion. All other elements were analyzed by optical emission spectroscopy. The results are listed in Table 2 and Table 3 compared to the requirements of ASTM A212 Grade B Firebox. All three specimens met the stated requirements.

2.5 Mechanical Testing

Tensile testing, Charpy V-notch impact testing (CVN), and fracture toughness testing was performed on specimens machined from both the ruptured EA-425B shell and the parallel EA-425A reboiler shell. A drawing of the two reboilers indicated plate from the same lot was used in fabrication of both, and the rupture of EA-425B invariably caused some changes in the mechanical properties of the shell. Chemical analysis results supported the indication that steel from the same lot was used for both shells. It was reported that the coupons from the EA-425A shell were cut from the side away from the EA-425B reboiler, which would minimize possible effects from the post rupture fire. Metallography and chemical analysis of samples from both shells supported the U-1 certificate indications that the EA-425A shell and EA-425B shell were from the same lot of steel.

2.5.1 Charpy V-notch Impact Testing

Charpy V-notch impact (CVN) testing was performed on specimens machined from EA-425B shell samples 164-4.01, 164-3.01, and EA-425A shell coupon 1. The notch direction of the specimens was parallel to the longitudinal axis of the reboiler shells. Tests were performed at temperatures from 10 °F to 250 °F in accordance with ASTM A370.² Results are listed in Table 4 through Table 6.

Absorbed energy results and fracture appearance as percent shear were plotted versus temperature, and curve fits through the data were performed as outlined in API 579-1³ using a

² ASTM A370-12, Standard Test Methods and Definitions for Mechanical Testing of Steel Products

³ API 579-1/ASME FFS-1, Fitness for Service, p. F-13, June 5, 2007



hyperbolic tangent function. Plots are shown in Figure 73. According to ASME Section VIII, Figure UG-84.1, the minimum CVN absorbed energy at the minimum design temperature for pressure shell material with specified 38-ksi yield strength such as ASTM A212 Grade B Firebox, is 15-ft-lbs.⁴ Test results for the EA-425A shell met this requirement at temperatures of 50 °F and above. The fit line through fracture appearance data indicated the 50% shear temperature was 100 °F for the EA-425A shell specimens. Equivalent impact energies and fracture appearance of specimens from the EA-425B shell were shifted to higher temperatures compared to the EA-425A shell, likely the result of plastic strains caused by the rupture.

2.5.2 Tensile testing

Tensile testing was performed on 0.505-inch diameter round specimens machined from reboiler EA-425B samples 164-1 and 164-3, and from EA-425A coupon 1. The button head specimen geometry was machined without the need to flatten the shell coupons. The tests were performed in accordance with ASTM A370.⁵ Measured crosshead displacement through yield was approximately 0.050-inch/minute. The maximum free running crosshead displacement rate allowed by the standard A370 is about 0.141-inch/minute for the specimen size used in this work. Metallography indicated that the plate longitudinal direction was oriented in the shell circumferential direction of both reboilers. Room temperature (70 °F) results are listed in Table 7 compared to the requirements of ASTM A212 Grade B Firebox. The EA-425B specimens had greater yield strength and tensile strengths with less elongation than the EA-425A specimens, consistent with shell work hardening during the rupture.

Elevated temperature tensile tests were performed to support fracture toughness testing and fracture modeling work. Test temperatures of 130 °F and 180 °F were selected to match the estimated shell temperature at the time of rupture, with the upper temperature of 180 °F determined by the temperature of the quench water. Elevated temperature tensile test results are listed in Table 8 and Table 9. Stress strain plots of the elevated temperature tests are shown in Figure 74.

2.5.3 Fracture Toughness Testing

Fracture toughness testing was performed by Hy-Performance Materials Testing⁶ in accordance with ASTM E1820⁷ on compact tension (CT) specimens machined from reboiler shells EA-425B and EA-425A. The specimen loading direction was parallel the circumferential direction of the reboiler shell and the crack plane was parallel to the longitudinal direction of the reboiler shell. This specimen orientation resulted in crack growth in the specimens consistent with the longitudinal fracture of the reboiler. The specimen geometry and nominal dimensions are shown in Figure 75. During the tests, crack length was calculated using the direct current potential drop (DCPD) method, which allowed J-integral fracture toughness to be obtained from each specimen tested. Test temperatures were selected to match the estimated shell temperature range at the time of rupture, with the upper temperature of 180 °F determined by the temperature of the

⁴ ASME Section VIII, Figure UG-84.1, GENERAL NOTES: (b) Minimum impact energy for one specimen shall not be less than 2/3 of the average energy require for three test specimens. The average impact energy of the three specimens may be rounded to the nearest ft-lb.

⁵ ASTM A370-12, Standard Test Methods and Definitions for Mechanical Testing of Steel Products

⁶ Hy-Performance Materials Testing, LLC, 17676 Paladin Drive Bend, OR 97701

⁷ ASTM E1820-13, Standard Test Method for Measurement of Fracture Toughness

quench water. Some tests were performed at 105 °F and 80 °F to explore the fracture behavior at the lower possible limits of temperature on the day of the rupture. The test matrix is listed in Table 10 and the results are summarized in Table 12. Plots of the resulting crack growth resistance curves are shown in Figure 76.

Test specimen crack fronts in the EA-425B shell specimens were uneven, and in some cases violated the acceptance criteria of ASTM E1820. This was likely caused by residual strains from the rupture event. Consequently, fracture toughness data from the EA-425A shell specimens was used for the modeling described in Section 2.6. All of the results at temperatures above 80 °F produced stable ductile fracture throughout the tests. Stable, predominantly ductile fracture with some cleavage was obtained in specimens tested at 80 °F.

2.6 Fracture Modeling

In an effort to help understand the range of pressure that caused the EA-425B shell rupture, finite element modeling was performed to estimate the lower bounds of internal pressure that could cause crack growth in the reboiler shell. Modeling was performed by Measurement Analysis Corporation (MAC)⁸ using multiple three dimensional models that incorporated tensile and fracture toughness data described in Section 2.5. The solid models incorporated relevant as-built details of the North outlet where fractography indicated shell rupture initiated, and included three different representations of the partial penetration longitudinal seam weld in the outlet pad. To save computation resources, the south half of the exchanger was not modeled. Accurately modeling the singular stress field surrounding the tip of a crack can require extremely refined mesh densities for an accurate FEA analysis. A recently developed FEA technique, termed the extended finite element method (XFEM), overcomes this difficulty by using enriched elements that incorporate the crack-tip singular fields and allow for displacement discontinuity across the elements that the fracture has penetrated.

Abaqus has XFEM capability, and the models presented in the report make use of this numerical methodology for modeling fractures. One can therefore say with certainty that the models accurately represented the singular stress field surrounding the crack-tip. Additionally, the virtual crack closure technique (VCCT) was used in conjunction with XFEM to accurately model crack initiation and growth. The MAC report is shown in Appendix D.

The XFEM implementation in Abaqus does not require an initial crack in the material; crack formation and propagation can occur in bulk material without an existing crack. However, limiting the size of the crack enrichment region can reduce computational expense. Therefore, enrichment regions, referred to in the MAC report as cracks, were included in the model where fracture initiation sites 1 and 2 had been identified. Several configurations along the longitudinal axis of the outlet pad weld were modeled. The blunted notch and the sharp notch configurations were physical crack configurations. The physical crack configurations take advantage of the XFEM implementation in Abaqus which allows an easy method to create cracks that are allowed to propagate.

As the summary of modeling results in Appendix D indicates, the lowest internal pressure that caused crack growth was 674-psi, with unstable crack growth at 1130-psi. This model, 7b, used a lower “derated” fracture energy release rate in the outlet pad seam weld and pad to shell fillet

⁸ Measurement Analysis Corporation, 23850 Madison Street, Torrance, CA 90505



weld than was measured using specimens from the shell. Weld metal typically has lower fracture toughness than wrought base metal, but the scope of this work did not include fracture toughness testing of the welds, so the welds were modeled with a derated value consistent with accepted trends in fracture toughness between base metal and weld metal. The incomplete penetration section of outlet pad longitudinal seam was represented as a planar crack surface, not an enrichment region. Because the section of incomplete penetration in the physical shell was as-flame cut, shown in Figure 19a and Figure 20a and represented in Figure 77, the geometry may be better represented by model 7b or model 7h, which used blunted notch and sharp/triangular notch geometries, respectively. The greatest internal pressure required to grow cracks was obtained from model 7, which used a blunted notch in the outlet pad seam weld. Crack growth initiated at 1212-psi with unstable crack growth at 1428-psi.

The location of initial crack growth varied between initiation site 1, initiation site 2, and the partial penetration weld of the outlet pad, depending on the model details. It is interesting to note that model 7d predicted crack growth through the full thickness of the outlet pad, then at site 2 and finally at site 1, described on page 15 of the MAC report. This suggests that shell fracture may have initiated at site 2 after the outlet pad seam weld had fractured. Regardless of the model result details, the range of pressures calculated to initiate crack growth provide insight into the possible mechanisms of the over pressure event, and agree with reported predictions based on confined thermal expansion of process liquids blocked into the shell side of the ruptured reboiler.⁹

3.0 SUMMARY AND DISCUSSION

Visual examination identified four shell fracture initiation sites, arbitrarily labeled 1 through 4, and the fracture directions between initiation sites as shown in Figure 32. Based on the post-rupture physical orientation of the shell and outlet piping, the directions and distances of fracture propagation, and the fracture modeling results, shell rupture first initiated at or near site 2. No evidence was found of cracks pre-existing the rupture event. The circumferential shell fractures resulted from bifurcation of the longitudinal fracture. Outlet piping fractures were caused directly and indirectly from the shell rupture. For example, the shell longitudinal fracture propagated directly into the north end outlet, sample 160-1, and the outlet crossover connection to the fractionator tower, sample 160-2, fractured from the energy released by the shell rupture.

Microscopic examination of shell fracture specimens indicated a predominance of cleavage morphology. For a given steel, increasing the crack propagation rate or decreasing the temperature will promote cleavage fracture. Fracture toughness testing at 180 °F, the temperature estimated for the shell at the time of rupture, indicated good fracture toughness and stable crack growth up to nearly 7-mm (0.28-inches). Macroscopic evaluation of fracture toughness test specimens indicated predominantly dimpled morphology indicative of ductile crack extension. Evidence of ductile fracture was found in the outlet pad seam weld above fracture initiation site 2, and fracture model results indicated the outlet pad seam weld as a likely location of fracture initiation. Assuming ductile fracture had initiated first in the outlet pad seam weld, the growing crack and resulting stress state just below the pad to shell fillet weld likely promoted cleavage fracture initiation at site 2. Because on-site post rupture corrosion was most extensive at the north end of the reboiler where fracture initiated, some ductile character at

⁹ Dan Tillema, CSB, verbal communication.



initiation site 2 may have been obscured or destroyed by corrosion. Some ductile morphology was detected in welds, such as the weld remnants on the inside surface of the shell at site 1, and in the outlet pad seam weld near site 2.

Fracture toughness testing and fracture modeling focused on temperatures of 130 °F to 180 °F because that is a likely range of shell temperature at the time of rupture based on the temperature of the quench water and time between introducing quench water to the ruptured reboiler tubes and the rupture event. The primary objective of the modeling was to identify the lower bounds of pressure required to initiate crack growth at the origins identified by fractography. The identified pressures are well above the maximum allowable working pressure and hydrostatic test pressure of the reboiler shell, and should help to understand the possible mechanisms of the overpressure event that caused rupture.

4.0 CONCLUSIONS¹⁰

The following conclusions are based upon the submitted samples and the evidence gathered:

1. Fracture of reboiler EA-425B likely initiated in the outlet pad longitudinal seam weld and the growing crack initiated fracture in the shell heat affected zone of the outlet pad to shell fillet weld, at initiation site 2.
2. The chemical composition of the EA-425B and EA-425A shells met the requirements for ASTM A212 Grade B Firebox steel.
3. Charpy V-notch impact testing indicated the EA-425A shell had a Charpy impact toughness of 18-ft-lbs (average of three tests) at 50 °F and a ductile to brittle transition temperature based on 50% shear fracture appearance of 100 °F. The impact test results indicated a shift in absorbed energy and fracture appearance values of the EA-425B specimens to higher temperatures compared to equivalent values for the EA-425A shell.
4. Tensile testing indicated the EA-425A and EA-425B shells met the tensile requirements for ASTM A212 Grade B Firebox steel, and indicated some effects of the rupture on tensile properties of the EA-425B specimens.
5. Fracture toughness testing of specimens machined from the EA-425A shell indicated good fracture toughness and stable crack growth during tests at 130 °F and 180 °F, the likely temperature range of the EA-425B reboiler shell at the time of rupture.
6. Fracture modeling indicated pressures required to initiate fracture were well above the maximum allowable working pressure and hydrostatic test pressure of the reboiler shell, and should help to understand the possible mechanisms of the overpressure event that caused rupture.

Prepared by:



Sam McFadden, Ph.D.
Associate Director of Laboratories

Reviewed by:



Ken Pytlewski, P.E.
Director of Engineering and Laboratories

¹⁰ The conclusions in this report are based upon the available information and evidence provided by the client and gathered by Anamet, within the scope of work authorized by the client, and they are hereby presented by Anamet to a reasonable degree of engineering and scientific certainty. Anamet reserves the right to amend or supplement its conclusions or opinions presented in this report should additional data or information become available, or further work be approved by the client.



Table 1
List of EA-425B shell Samples Received by Anamet

Section Identification Number	Identification Tag Description
164-1	Shell section 1
164-2	Shell section 2
164-3	Shell section 3
164-4	Shell section 4
164-5	Shell section 5
117	Piece of EA-425B shell
160-1	Propylene outlet pipe (above) crossover section 1
160-2	Propylene outlet pipe (above) crossover section 2
122	Fractionator pipe and flange, tower conn. section 2
138	Flange/pipe "crossover section 3"
113A-1	Pipe (w/o valve) tower (frac) connection section 1

Table 2
Results of Quantitative Chemical Analysis of
EA-425B Reboiler Shell Specimens Compared to ASTM A212 Grade B, Firebox

Element	Sample 164-1.01 (wt%)	Sample 164-3.01 (wt%)	Requirements for ASTM A212 Grade B Firebox (wt%)	
			min	max
Aluminum (Al)	<0.005	<0.005	-.-	-.-
Carbon (C)	0.25	0.24	-.-	0.31
Chromium (Cr)	0.04	0.14	-.-	-.-
Columbium (Cb)	<0.005	<0.005	-.-	-.-
Copper (Cu)	0.07	0.11	-.-	-.-
Iron (Fe)	Balance	Balance	Balance	
Manganese (Mn)	0.68	0.68	-.-	0.90
Molybdenum (Mo)	0.02	0.04	-.-	-.-
Nickel (Ni)	0.07	0.10	-.-	-.-
Phosphorus (P)	0.008	0.007	-.-	0.035
Silicon (Si)	0.15	0.25	0.13 ^A	0.33 ^A
Sulfur (S)	0.018	0.015	-.-	0.04
Titanium (Ti)	<0.005	<0.005	-.-	-.-
Vanadium (V)	<0.005	<0.005	-.-	-.-

^A Check analysis requirements



Table 3
Results of Quantitative Chemical Analysis of
EA-425A Reboiler Shell Specimen Compared to ASTM A212 Grade B, Firebox

Element	Coupon 1 (wt%)	Requirements for ASTM A212 Grade B Firebox (wt%)	
		min	max
Aluminum (Al)	0.005	-.-	-.-
Carbon (C)	0.26	-.-	0.31
Chromium (Cr)	0.15	-.-	-.-
Columbium (Cb)	<0.005	-.-	-.-
Copper (Cu)	0.12	-.-	-.-
Iron (Fe)	Balance	Balance	
Manganese (Mn)	0.70	-.-	0.90
Molybdenum (Mo)	0.04	-.-	-.-
Nickel (Ni)	0.10	-.-	-.-
Phosphorus (P)	0.007	-.-	0.035
Silicon (Si)	0.26	0.13 ^A	0.33 ^A
Sulfur (S)	0.013	-.-	0.04
Titanium (Ti)	<0.005	-.-	-.-
Vanadium (V)	<0.005	-.-	-.-

^A Check analysis requirements



Table 4
Charpy V-Notch test Results for EA-425B Reboiler Shell Section 164-4.01

Test Temperature (°F)	Energy Absorbed (ft·lbs)	Lateral Expansion (mils)	Fracture Appearance (% Shear)
50	8	11	5
	10	13	9
	6	8	9
70	16.5	21	25
	29	31	30
	21	25	27
90	25	28	30
	28	31	27
	11	16	23
130	48	48	48
	40	44	48
	48	47	54
170	66	66	91
	66	68	90
	68	70	>98
210	71	70	>98
	70	72	>98
	68	68	>98



Table 5
Charpy V-Notch Test Results for EA-425B Reboiler Shell Section 164-3.01

Test Temperature (°F)	Energy Absorbed (ft·lbs)	Lateral Expansion (mils)	Fracture Appearance (% Shear)
50	6	6	9
	4	5	9
	4	3	5
70	23	24	20
	13	15	14
	7	9	14
90	11	15	13
	22	24	27
	11	14	14
130	32	37	40
	30	36	38
	47	50	59
170	64	64	>98
	59	60	>98
	69	69	>98
210	60	65	>98
	75	70	>98
	66	67	>98



Table 6
Charpy V-Notch Test Results for EA-425A Reboiler Shell Coupon 1

Test Temperature (°F)	Energy Absorbed (ft·lbs)	Lateral Expansion (mils)	Fracture Appearance (% Shear)
10	7	6	9
	6	9	9
	9	10	9
50	20	23	18
	12	15	18
	22	23	20
70	26	30	33
	35	35	38
	30	32	29
90	31	34	42
	30	32	43
	29	29	37
130	58	58	77
	49	47	59
	54	50	67
170	70	70	>98
	71	62	>98
	69	55	>98
210	70	57	>98
	70	66	>98
	75	69	>98
250	66	69	>98
	69	64	>98
	68	70	>98



Table 7
Room Temperature Tensile Test Results

Reboiler Shell	Section	Specimen ^A	Tensile Strength (ksi)	Yield Strength (ksi)	Elongation In 2-inches
EA-425B	164-4.01	4L-1	78.8	59.9	23 ½
		4L-2	78.8	59.4	23
		4L-3	78.9	54.6	22 ½
		4T-1	78.1	56.0	22
		4T-2	78.7	56.2	22 ½
		4T-3	78.2	59.3	24
EA-425B	164-3.01	3L-1	78.6	56.6	28 ½
		3L-2	79.3	57.8	26
		3L-3	79.5	59.1	27
		3T-1	80.6	64.4	22
		3T-2	81.9	68.9	20 ½
		3T-3	81.7	67.9	20
EA-425A	1	T1	77.5	42.9	31
		T2	77.3	45.3	31
		T3	77.3	42.8	31
EA-425A	1	L1	77.6	41.0	31 ½
		L2	77.6	42.0	33 ½
		L3	77.5	40.6	32
Requirements ASTM A 212 Grade B, Firebox			70.0 to 85.0	38.0 (minimum)	22 (minimum)

^A L indicates tensile axis oriented in the shell circumferential direction (plate rolling direction) and T indicates tensile axis oriented in the shell longitudinal direction (plate transverse direction).



Table 8
130 °F Tensile Test Results

Reboiler Shell	Section	Specimen ^A	Tensile Strength (ksi)	Yield Strength (ksi)	Elongation In 2 Inches
EA-425B	164-1.03	BL130-1	73.1	50.4	25
		BL130-2	72.8	50.0	27
EA-425A	1	L1301	74.7	41.0	33
		L1302	75.2	41.3	33 ½

Table 9
180 °F Tensile Results

Reboiler Shell	Section	Specimen ^A	Tensile Strength (ksi)	Yield Strength (ksi)	Elongation In 2 Inches
EA-425B	164-1.03	BL180-1	70.8	47.8	28
		BL180-2	71.3	49.3	25
EA-425A	1	L1801	73.5	40.5	31 ½
		L1802	72.8	39.6	30



Table 10
Fracture Toughness Test Matrix and Summary of Results

Reboiler	Specimen	Temp (°F)	B (in)	B _N (in)	J _{init} (kJ/m ²)	K _{init} (MPa√m)	J _{IC} (kJ/m ²)	K _{JIC} (MPa√m)
EA-425B	1	130	0.500	0.381	82	137	103	153
	2	130	0.500	0.421	101	152	138	177
	4	130	0.500	0.381	66	123	87	141
	6	130	0.500	0.381	70	126	118	164
	3	180	0.500	0.379	78	133	118	164
	5	180	0.501	0.382	70	126	89	142
EA-425A	4	80	0.501	0.379	103	153	153	187
	8	80	0.500	0.420	65	121	156	188
	9	80	0.701	0.525	49	105	104	154
	1	105	0.501	0.379	101	151	141	179
	5	105	0.500	0.380	62	118	115	162
	12	105	0.701	0.525	77	132	141	179
	2	130	0.501	0.379	122	167	164	193
	7	130	0.500	0.381	89	142	148	184
	10	130	0.701	0.522	111	159	161	192
	11	130	0.701	0.525	58	114	127	170
	3	180	0.500	0.376	78	133	118	164
	6	180	0.500	0.380	88	142	129	171





Figure 1 Photograph of the ruptured reboiler viewed from the north end, taken on July 10, 2014.



Figure 2 Photograph of the ruptured reboiler viewed from the north end, courtesy of the CSB.




(a) North end



(b) South end

Figure 3 Subject reboiler heads, tube sheets, tubes, and remnant shell removed from the incident site to a tented area of the refinery.



(a)



(b) Boxed area in (a)

Figure 4 Ruptured tubes. Necked ends indicated overload fracture that resulted from the shell rupture.




Figure 5 The ruptured section of reboiler shell removed from the incident site to a tented area of the refinery. The view is from the south. Tubes, tube sheet, and head of the reboiler are visible in the lower left.






Figure 6 Schematic of three major fracture paths in the reboiler shell



(a) North end



(b) West side

Figure 7 The ruptured section of reboiler shell in a tented lay-down area of the refinery.




Figure 8 Fragment from shell, section 117.



Figure 9 Ruptured north end outlet, section 160-1, sectioned from the boxed area in Figure 1.



(a)



(b)

Figure 10 Ruptured shell section marked for cutting. The shell was flame cut along yellow lines drawn on the inside surface, and the resulting sections were assigned the identification numbers indicated.



Figure 11 Ruptured shell section marked for cutting. The shell was flame cut along yellow lines drawn on the inside surface, and the resulting sections were assigned the identification numbers indicated.



Figure 12 Photograph of coupon 1 from reboiler EA-425A shell.



Figure 13 Photograph of coupon 2 from reboiler EA-425A shell.




Figure 14 Shell section 164-1.



Figure 15 Shell section 164-2.




Figure 16 Shell section 164-3. The test specimen coupon was flame cut from the section after visual examination of the fracture surface.

Initiation site 3

Initiation site 2

Initiation site 1






Figure 17 Shell section 164-4.



Figure 18 Shell section 164-5.




(a) 164-4




(b) 164-1

Figure 19 Fracture surface photographs site 1.



(a) Fracture surface, boxed area in Figure 19b



(b)

Figure 20 Fracture initiation site 1, specimen 164-1.01.1. The dashed line in (b) indicates the toe of the groove weld that joined the outlet to the shell, etched with 2% nital.



Figure 21 Macrograph of cracks in weld on shell inside surface of specimen 164-1.01.1, initiation site 1, from the boxed area in Figure 20. Surface was lightly ground with 240-grit silicon carbide paper and etched with 2% nital.







Figure 22 Fracture surface photographs site 2.




(a) Boxed area in Figure 22



(b) Boxed area in (a)

Figure 23 Fracture initiation site 2, specimen 164-4.02.2. After cleaning with Citrinex®. The dashed line in (b) indicates the shell surface below the shell to outlet pad fillet weld.




(a) 164-4




(b) 164-1

Figure 24 Fracture surface photographs circumferential weld.




(a) 164-4




(b) 164-1

Figure 25 Fracture surface photographs, initiation site 3.



(a) Specimen 164-1.02.2



(b) Specimen 164-4.03

Figure 26 Fracture initiation site 3, specimens 164-1.02.2 and 164-4.03. In (b), the specimen had been cleaned with Citrinox® and the outside surface was ground through 400 grit silicon carbide paper, and etched with 2% nital.



(a) 164-3




(b) 164-2

Figure 27 Fracture surface photographs, fracture tee junction. In (b), the convergence of two fracture directions indicates the north end of section 117 shown in Figure 8.



(a) 164-3




(b) 164-2

Figure 28 Fracture surface photographs, initiation site 4. In (a), the corner indicates the south end of section 117 shown in Figure 8.



(a) Pattern of arc gouges on section 164-2



(b) 164-3
Figure 29 Photograph of section 164-3.




(a)



(b)

Figure 30 Photographs of section 164-5 fracture surface.




(a)




(b)

Figure 31 Photographs of section 164-5 fracture surface.




(a) 164-1.03




(b) Section indicated in (a)

Figure 32 Photographs of specimens from section 164-1, shell to north end tube sheet fracture.



(a)

- Fracture propagation direction toward the south
- Fracture propagation direction toward the north
- Fracture propagation direction circumferential



(b)

Figure 33 Fracture path maps. Fracture initiation sites, arbitrarily labeled 1 through 4, and directions of fracture propagation were indicated by chevron marks. The map in (a) was drawn from tracing the fracture surfaces of sections 164-1, 164-2, 164-3, 164-4, and 117.




(a) 160-1




(b) 160-2

Figure 34 Ruptured outlet samples 160-1 and 160-2.



(a) Boxed area 1 in Figure 34



(b) Boxed area 2 in Figure 34

Figure 35 Photographs of ruptured outlet fracture surfaces.






Figure 36 Photograph of fracture initiation site 1, section 164-1.01.1. Boxed areas indicate locations from which SEM micrographs were taken. Sample had been cleaned in 20% Citrinex® with ultrasonic agitation.




(a)




(b) Boxed area in (a)

Figure 37 SEM micrographs of initiation site 1 from the location 1A indicated in Figure 36.




(a)




(b) Boxed area in (a)

Figure 38 SEM micrographs of initiation site 1 from the location 1B indicated in Figure 36.




(a)




(b) Boxed area in (a)

Figure 39 SEM micrographs of initiation site 1 from the location 1C indicated in Figure 36.




(a)




(b) Boxed area in (a)

Figure 40 SEM micrographs of initiation site 1 from the location 1D indicated in Figure 36.



(a)




(b) Boxed area in (a)


Figure 41 SEM micrographs of initiation site 1 from the location 1E indicated in Figure 36.



Figure 42 Photograph of fracture initiation site 2 cut from section 164-4. Boxed areas indicate locations from which SEM micrographs were taken. Sample had been cleaned in 20% Citrinex® with ultrasonic agitation.




(a)




(b) Boxed area in (a)

Figure 43 SEM micrographs of fracture initiation site 2 from location 2A indicated in Figure 42.




(a)




(b) Boxed area in (a)

Figure 44 SEM micrographs of fracture initiation site 2 from location 2B indicated in Figure 42.




(a)




(b) Boxed area in (a)

Figure 45 SEM micrographs of fracture initiation site 2 from location 2C indicated in Figure 42.




(a)




(a) Boxed area in (a)

Figure 46 SEM micrographs of fracture initiation site 2 from location 2D indicated in Figure 42.




(a)




(b) Boxed area in (a)

Figure 47 SEM micrographs of fracture initiation site 2 from location 2E indicated in Figure 42.



(a)



(a)

Figure 48 SEM micrographs of fracture initiation site 2 from location 2F indicated in Figure 42.






Figure 49 Fracture initiation site 3 with SEM micrograph locations indicated.




(a)




(b) Boxed area in (a)

Figure 50 SEM micrographs of initiation site 3 from location 3A indicated in Figure 49.




(a)




(b) Boxed area in (a)

Figure 51 SEM micrographs of fracture initiation site 3 from location 3B indicated in Figure 49.



(a)



(b) Boxed area in (a)

Figure 52 SEM micrographs of fracture initiation site 3 from location 3C indicated in Figure 49.




Figure 53 Fracture initiation site 4 with SEM micrographs indicated.






Figure 54 SEM micrograph of arc gouge at fracture initiation site 4 from location 4A indicated in Figure 53.




(a)




(b)

Figure 55 SEM micrographs of fracture initiation site 4 from location 4B indicated in Figure 53.



(a)



(b)

Figure 56 SEM micrographs of fracture initiation site 4 from location 4C indicated in Figure 53.



(a)



(b) Boxed area in (a)

Figure 57 Shell section 164-4 after sectioning. The dashed lines in (a) indicate sections prepared for metallography.



(a) As-polished



(b) Etched with 2% nital

Figure 58 Optical micrographs of a shell circumferential section from section 164-4.01.



(a) As-polished




(b) Etched with 2% nital

Figure 59 Optical micrographs of a shell longitudinal section from section 164-4.01.



(a)




(b)

Figure 60 Shell section 164-3 after sectioning




(a) As-polished



(b) Etched with 2% nital

Figure 61 Optical micrographs of a shell circumferential section from section 164-3.01.




(a) As-polished




(b) Etched with 2% nital

Figure 62 Optical micrographs of a shell longitudinal section from section 164-3.01.




(a) Specimen 164-4.02.2




(b)

Figure 63 Fracture initiation site 2 and a specimen prepared for metallography from a section cut 0.5-inch below the fracture plane shown.



(a)




(b)

Figure 64 Optical micrographs of the pad to shell fillet weld from location 1 indicated in Figure 63b. Knoop microhardness indentations are visible in each micrograph.




(a)




(b)

Figure 65 Optical micrographs of the pad to shell fillet weld from location 2 indicated in Figure 63b. Knoop microhardness indentations are visible in each micrograph.




(a)




(b)

Figure 66 Optical micrographs of the shell from location 3 indicated in Figure 63b. Knoop microhardness indentations are visible in each micrograph




(a) As-polished




(b) Etched with 2% nital

Figure 67 Optical micrographs of a longitudinal specimen from the EA-425A reboiler shell.



(a) As-polished



(b) Etched with 2% nital

Figure 68 Optical micrographs of a circumferential section of the EA-425A reboiler shell.





Figure 69 Knoop microhardness survey results from along the dashed line indicated in Figure 63b.




(a)




(b)

Figure 70 Fracture initiation site 2 and a specimen prepared for metallography from a section through the outlet pad indicated by the dashed lines in (a).




(a)



(b)

Figure 71 Optical micrographs of the outlet pad partial penetration seam weld from the location δ indicated in Figure 70b.




(a)




(b)

Figure 72 Optical micrographs of the outlet pad heat affected zone location ϵ indicated in Figure 70b.



(a)



(b)

Figure 73 CVN results, (a) absorbed energy plots and (b) % shear plots with fit lines..




Figure 74 Stress-strain plots of elevated temperature tensile tests of EA-425A shell coupon 1.




Figure 76 Crack growth resistance curves.




Figure 77 Representation of the outlet pad geometry.



Appendix B
(Courtesy of the CSB and Williams Olefins)

75827-EA425B-4A

FORM U-1 MANUFACTURERS' DATA REPORT FOR UNFIRED PRESSURE VESSELS
As required by the Provisions of the ASME Code Rules

S/O 50941

1. Manufactured by DELTA SOUTHERN COMPANY - BATON ROUGE, LOUISIANA
(Name and address of manufacturer)
2. Manufactured for THE LUMMUS COMPANY, HOUSTON, TEXAS
(Name and address of Purchaser)
3. Type Horiz. Kind Heat Exch. Vessel No. (50941-67-2) (Mfrs. Serial) (State & State No.)
Natl. Bd. No. 2085 Yr. Built 1967

Items 4-9 incl. to be completed for single wall vessels (such as air tanks), jackets of jacketed vessels, or shells of heat exchangers.

4. SHELL: Material SA-212-B-FBQ T.S. 70,000 Nominal 11/16 Corrosion 1/16
(Kind and Spec. No.) (Fig. or P.B. & Spec. Min. T.S.) Thickness In. Allowance In. Diam. 5 Ft. 1 In. Length 18 Ft. 5-3/4" I.D. 18 LOS
5. SEAMS: Long Dbl. Butt. H.T. No X.R. Spot Sectioned No Efficiency 85 %
(Welded, Dbl., Single, Lap, Butt) (Yes or No) (Spot or Complete) (Yes or No)
Girth Dbl. Butt. H.T. No X.R. Spot Sectioned No No. of Courses 3
6. HEADS: (a) Material - T.S. - (b) Material - T.S. -
Location Thickness Crown Radius Knuckle Radius Elliptical Ratio Conical Apex Angle Hemispherical Radius Flat Diameter Side to Pressure
(Top, bottom, ends) (Convex or Concave)
(a) - - - - - - - - -
(b) - - - - - - - - -
If removable, bolts used - Other fastening - (Describe or Attach Sketch)
7. STAYBOLTS: - If hollow - Attachment - Pitch X Diam. -
(Material) (Size of Hole) (Threaded, Welded) (Horiz.) (Vert.) (Nominal)
8. JACKET CLOSURE: - (Describe as ogee & weld, bar, etc. If bar give dimensions, if bolted, describe or sketch)
9. Constructed for max. allowable working press. 300 psi. at max. temp. 200 °F. Min. temp. (when - °F. less than -20°) - °F. Hydrostatic Test 450 psi.
Pneumatic or Combination Press.

Items 10 and 11 to be completed for tube sections.

10. TUBE SHEETS: Stationary. Material SA-212-B-FBQ Diam. 6 7/8 In. Thickness 3-1/8" Attachment Bolted
(Kind & Spec. No.) (Subject to Pressure) (Welded, Bolted)
Floating. Material SA-212-B-FBQ Diam. 6 7/8 In. Thickness 3-1/8" Attachment Bolted
(Kind & Spec. No.)
11. TUBES: Material SA-214 O.D. 3/4" Ø In. Thickness .085" (Min. Inches of Gage) Number 3020 Type Straight
(Kind & Spec. No.) (Straight or U)

Items 12-15 incl. to be completed for shells of jacketed vessels or channels of heat exchangers.

12. SHELL: Material SA-212-B-FBQ T.S. 70,000 Nominal 11/16 Corrosion 1/8
(Kind and Spec. No.) (Fig. or P.B. & Spec. Min. T.S.) Thickness In. Allowance In. Diam. 5 Ft. 1 In. Length 18 Ft. 9" I.D. 18 L.O.C.
13. SEAMS: Long Dbl. Butt. H.T. Yes X.R. Spot Sectioned No Efficiency 85 %
(Welded, Dbl., Single, Lap, Butt) (Yes or No) (Spot or Complete) (Yes or No)
Girth Dbl. Butt. H.T. Yes X.R. Spot Sectioned No No. of courses 1
14. HEADS: (a) Material - T.S. - (b) Material SA-212-B-FBQ T.S. 70,000 (c) Material - T.S. -
Location Thickness Crown Radius Knuckle Radius Elliptical Ratio Conical Apex Angle Hemispherical Radius Flat Diameter Side to Pressure
(Top, bottom, ends) (Convex or Concave)
(a) - - - - - - - - -
(b) Channel Ends 11/16" 61" 3-11/16" - - - - - Concave
(c) Floating - - - - - - - - -
If removable, bolts used (a) - (Material, Spec. No., T.S., Size, Number) (b) SA-193-B7, 120,000, 7/8", 72
(c) - Other fastening - (Describe or Attach Sketch)
15. Constructed for max. allowable working press. 157 psi. at max. temp. 220 °F. Min. temp. (when - °F. less than -20°) - °F. Hydrostatic Test 235 psi.
Pneumatic or Combination Press.

Items below to be completed for all vessels where applicable.

16. SAFETY VALVE OUTLETS: Number - Size - Location In Line

17. NOZZLES:

Purpose (Inlet, Outlet, Drain)	Number	Diam. or Size	Type	Material	Thickness	Reinforcement Material	How Attached
Inlet & Outlet	2	12"	150# RFSO	SA-106-B	Sch. 80	None	Welded
Outlet	1	16"	300# RFSO	SA-106-B	X-Stg.	None	Welded
Inlet	1	18"	300# RFWN	SA-212-B-FBQ	1/2"	SA-212-B-FBQ	Welded

18. INSPECTION Manholes, No. - Size - Location -

OPENINGS: Handholes, No. - Size - Location -

Threaded, No. - Size - Location -

19. SUPPORTS: Skirt No Lugs - Legs - Other Saddles Attached Welded to Shell
(Yes or No) (Number) (Number) (Describe) (Where & How)

20. REMARKS: P.O. No. T-5827-400 - Item No. EA-425-B Size: 61-240 Type: BJM
(One) 20" O.D. Jumper Pipe

(Brief description of purpose of the vessel, as Air Tank, After Cooler, Jacketed Cooker, etc. State contents of each part.) (Over)
* If postweld Heat-treated.



Appendix B
(Courtesy of the CSB and Williams Olefins)

FORM U-1 (back)

We certify that the statements made in this report are correct and that all details of design, material, construction, and workmanship of this vessel conform to the ASME Code for Unfired Pressure Vessels.

Date JAN 27 1967 19____ Signed DELTA SOUTHERN COMPANY By J.C. LeBlanc
(Manufacturer)

Certificate of Authorization Expires DECEMBER 31, 1967

CERTIFICATE OF SHOP INSPECTION

VESSEL MADE BY DELTA SOUTHERN COMPANY at BATON ROUGE, LOUISIANA

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and/or the State of LOUISIANA and employed by HARTFORD STEAM BOILER INSP. INS. CO. of HARTFORD, CONN. have inspected the pressure vessel described in this manufacturer's data report on JAN 27 1967 19____, and state that to the best of my knowledge and belief, the manufacturer has constructed this pressure vessel in accordance with the applicable sections of the ASME Boiler and Pressure Vessel Code.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the pressure vessel described in this manufacturer's data report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

Date JAN 27 1967 19____
[Signature]
Inspector's Signature

NAT'L BD. COMM:
NO. 1849
Net'l Board or State and No.

Commissions _____

CERTIFICATE OF FIELD ASSEMBLY INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and/or the State of _____ and employed by _____ of _____ have compared the statements in this manufacturer's data report with the described pressure vessel and state that parts referred to as data items _____, not included in the certificate of shop inspection have been inspected by me and that to the best of my knowledge and belief the manufacturer has constructed and assembled this pressure vessel in accordance with the applicable sections of the ASME Boiler and Pressure Vessel Code. The described vessel was inspected and subjected to a hydrostatic test of _____ psi.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the pressure vessel described in this manufacturer's data report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.


Date _____ 19____

Inspector's Signature _____ Commissions _____ Net'l Board or State and No. _____




Appendix C

Mode I loading



Mode III loading





Appendix D

MEASUREMENT ANALYSIS CORPORATION

**Fracture Analysis of Williams Olefins Vessel EA-425B
Accident of June 13, 2013 in Geismar, Louisiana**

for

Sam McFadden
Anamet, Inc.

26102 Eden Landing Road, Suite 3
Hayward, CA 94545

Prepared by: Don Schultz
Don Schultz, Senior Engineer
Measurement Analysis Corporation

Reviewed by: Robert Coppelino
Robert Coppelino, Ph D.
Chief Technology Officer
Measurement Analysis Corporation
January 6, 2015



Reference: Anamet, Inc. purchase order #15563

Measurement Analysis Corporation
23850 Madison Street, Torrance, CA 90505
310-378-5261



Appendix D

MEASUREMENT ANALYSIS CORPORATION

Executive Summary

This report describes the finite element modeling used to determine the internal pressure that could cause growth of any existing cracks or defects found in the vessel structure (as identified from the initial incident survey and inspection). This analysis emphasizes the response of the structure in the two regions of interest, including both where the failure of the vessel initiated, and the longitudinal weld of the doubler. The analysis effort included multiple 3D finite element models, with multiple crack configurations and fracture toughness properties, as well as empirically based analyses to confirm the finite element results.


The finite element results indicate that the lowest “overpressure event” that could lead to growth of any initial cracks would be 674 psig. This is based on an Abaqus version 6.14-1 model that incorporated the tensile test data and fracture toughness data for the vessel shell material (provided by Anamet, Inc.). Multiple analyses and models were used, varying the fracture energy release rate and crack configurations to determine the lower bound for the internal pressure that leads to crack growth.

Appendix D

MEASUREMENT ANALYSIS CORPORATION

General Description

The U.S. Chemical Safety Board (CSB) contracted Anamet, Inc. (Anamet) to be one of the primary accident investigators of the Williams-Olefins vessel rupture event. Anamet contracted Measurement Analysis Corp. (MAC) to perform a finite element analysis of the ruptured pressure vessel. The diagram below shows the two primary crack initiation locations, including the partial penetration weld along the doubler's longitudinal axis, used in the finite element model to represent the rupture event for the EA-425B vessel.




Appendix D

MEASUREMENT ANALYSIS CORPORATION

General Description (cont.)

The pressure vessel includes 3020 SA-214 tubes (0.750" OD with a 0.085" nominal wall thickness) that carry the "quench water". These tubes are press fit/swaged into the 3.125" thick tubesheet at both ends of the vessel and experience 157 psig internally. This 157 psig also loads the elliptical end caps. The interior of the pressure vessel is loaded to a maximum allowable working pressure (MAWP) of 300 psig. The nominal shell thickness is 0.6875". Note that *hydrostatic fluid loads have not been accounted for in these models* as the maximum hydrostatic load is only ≈ 0.66 psi at the *bottom* of the vessel, if 2/3 full of process fluid.





Appendix D

MEASUREMENT ANALYSIS CORPORATION

Analysis Approach

Modeling fracture using Abaqus can be done using a relatively new method to model propagating cracks. This method is referred to as XFEM (eXtended Finite Element Method). XFEM is a mesh independent fracture modeling methodology implemented in Abaqus that allows the user to determine crack initiation and propagation in the bulk material of models, with or without initial cracks. It allows the user to avoid modeling the crack surface with a focused mesh, and allows the internal solution to determine crack propagation and its direction.

The analysis models described here use a LEFM (linear elastic fracture mechanics) approach to represent quasi-static crack growth using VCCT (Virtual Crack Closure Technique). The elastic-plastic tensile test data are used within the LEFM approach to include material plasticity. Both existing cracks (modeled explicitly with a planar crack surface) and cracks that nucleate in bulk material can be represented. The use of LEFM with VCCT is appropriate for modeling brittle crack propagation.


The models shown here are the result of mesh studies done earlier. Further refinements to the models have been made to include the weld flexibility around the outer perimeter of the doubler, refinement of the tied contact interfaces, and incorporation of fracture mechanics.

Appendix D

MEASUREMENT ANALYSIS CORPORATION

Model Description

The model is a “half model” which includes the north end of the vessel, the tubesheet, and the elliptical end cap. The tubes are represented by *equivalent* area beam elements that are distributed on the interior of the pressure vessel and are connected to the tubesheet using kinematic constraints that apply only axial load. The nozzles near the mid-plane are not included in the model because the failure initiated in the region of where the “jumper pipe” enters the shell of the pressure vessel. Excluding the nozzles allows for a smaller analysis model.





Appendix D

MEASUREMENT ANALYSIS CORPORATION

Material Property Data

A summary of the linear-elastic derived material data used in the analysis model is shown below.



Item	Material	Young's Modulus (psi)	Poisson's Ratio	Yield Stress (psi)
Shell	SA-212-B	29,896,100	0.29	46,000
tubesheet	SA-212-B	29,896,100	0.29	46,000
doubler	SA-212-B	29,896,100	0.29	46,000
End cap	SA-212-B	29,896,100	0.29	46,000
Jumper pipe	SA-106-B	31,362,100	0.30	46,100
Tubes	SA-214	29,100,000	0.30	26,000

Appendix D

MEASUREMENT ANALYSIS CORPORATION

Material Property Data – stress/strain

The model material data was derived from recent tensile tests of the shell material (SA-212-B) using 0.505" diameter specimens. Multiple specimens were tested at 130°F and 180°F. The stress-strain curve used for the finite element models was the BL-180-1 curve with the lowest relative strength. The SA-106 stress strain data was derived from material testing not related to this incident.




Appendix D

MEASUREMENT ANALYSIS CORPORATION

Material Property Data – energy release rate

The fracture toughness data was derived from recent compact tensile tests of the shell material. Again, multiple specimens were tested at 130°F and 180°F. The baseline energy release rate ($\approx 504 \text{ in-lb/in}^2$) used for shell material is based on tests at the lower temperature of 130°F. However, most finite element models used a derated energy release rate (400 in-lb/in^2) in the region of the weld around the outer perimeter of the doubler and the longitudinal weld region of the doubler.




Appendix D

MEASUREMENT ANALYSIS CORPORATION

Model Description – Crack Locations

The cracks at site 1 and site 2 have a major axis dimension of 0.50" and a minor axis dimension of 0.25". Site 1 is partially embedded in the shell with its major axis parallel with the vessel axis and tangent to the vessel inside diameter. Site 2 is fully embedded in the shell just below the weld.



Elevation view of the shell (with crack sites 1 & 2), jumper pipe, doubler, and weld




Appendix D

MEASUREMENT ANALYSIS CORPORATION

Model Description – Crack configurations

Multiple crack configurations in the doubler



Note that the grey region in the doubler is the longitudinal region where the material can initiate crack growth



Appendix D

MEASUREMENT ANALYSIS CORPORATION

Results Summary

	A	B	C	D	E	F	G
1				Crack Region		Pressure at Initial	Pressure at unstable
2				Fracture Energy			
3				Release Rate	Region of initial Crack Growth	Crack Growth (psi)	Crack Growth (psi)
4	Model	Region	Crack Type	(lb/in)			
5	7	doubler	B	$J_{IC} = 400$	site 1 & 2	1212	1428
6		vessel site 1 (fwd)	A	$J_{IC} = 504$			
7		vessel site 2 (aft)	A	$J_{IC} = 504$			
8		weld	C	$J_{IC} = 400$			
9	7a	doubler	B	$J_{int} = 300, J_{IC} = 450$	site 1	1095	1295
10		vessel site 1 (fwd)	A	$J_{int} = 325, J_{IC} = 502$			
11		vessel site 2 (aft)	A	$J_{int} = 325, J_{IC} = 502$			
12		weld	C	$J_{int} = 300, J_{IC} = 450$			
13	7b	doubler	B	$J_{IC} = 325$	site 1	976	1278
14		vessel site 1 (fwd)	A	$J_{IC} = 325$			
15		vessel site 2 (aft)	A	$J_{IC} = 325$			
16		weld	C	$J_{IC} = 325$			
17	7d	doubler	A	$J_{IC} = 400$	doubler (aft)	674	1130
18		vessel site 1 (fwd)	A	$J_{IC} = 504$			
19		vessel site 2 (aft)	A	$J_{IC} = 504$			
20		weld	C	$J_{IC} = 400$			
29	7h	doubler	B'	$J_{IC} = 400$	site 1	1109	1362
30		vessel site 1 (fwd)	A	$J_{IC} = 504$			
31		vessel site 2 (aft)	A	$J_{IC} = 504$			
32		weld	C	$J_{IC} = 400$			
37	8e	doubler	A	$J_{IC} = 504$	doubler (aft)	718	962
38		vessel site 1 (fwd)	A	$J_{IC} = 504$			
39		vessel site 2 (aft)	A	$J_{IC} = 504$			
40		weld	C	$J_{IC} = 400$			
41							
42	Crack Types						
43	A: planar crack surface						
44	B: blunted notch						
45	B': triangular notch						
46	C: bulk material w/o initial crack surface						

Note that model-7d represents the configuration with the lowest pressure to initiate crack growth.

Model-7d also includes a "derated" fracture energy release rate for the longitudinal weld region that joins the left hand side and right hand side of the doubler.

Model-8e indicates a slightly higher value of internal pressure (718 psi) to initiate crack growth using "nominal" fracture energy release rate value in the longitudinal weld region of the doubler.



Appendix D

MEASUREMENT ANALYSIS CORPORATION

Results Summary (cont.)

The configuration of model-7 (blunted notch in the doubler with baseline fracture toughness values) and model-7d (sharp planar half-thickness crack in doubler with baseline fracture toughness values) bound the pressures required for initial crack propagation. Model-7 indicates 1212 psi to initiate crack growth at vessel site 2 (aft of the jumper pipe) and 1218 psi to initiate crack growth at vessel site 1, with the crack growth becoming unstable at 1428 psi. Model-7d indicates 674 psi to initiate crack growth in the aft doubler region, with the crack growth becoming unstable at 1130 psi.

Model-7a represents a variation of model-7 by using “enhanced” VCCT, which uses two fracture energy release rates to ramp down the resulting surface tractions over the element length. This approach can lead to smoother crack propagation with some additional computational expense. Regardless, model-7a shows the initial crack growth occurring at vessel site 1 (forward of the jumper pipe) at 1095 psi, and the crack becoming unstable at 1295 psi.

Model-7b is a variation of model-7 with the same blunted notch in the doubler, but with reduced fracture toughness values (325 lb/in vs 504 lb/in used in model-7). Model-7b showed the initial crack growth occurring at vessel site 1 (forward) at 976 psi, with the crack becoming unstable at 1278 psi.



Appendix D

MEASUREMENT ANALYSIS CORPORATION

Results Summary (cont.)

Model-7d is a variation of model-7 without the blunted notch in the doubler, but using a planar surface representing the crack. This planar surface is positioned along the full length of the doubler and has its initial crack surface half way through the doubler thickness. Model-7d showed the initial crack growth occurring at vessel site 1 (forward) at 674 psi, with the crack becoming unstable at 1130 psi. The crack propagates through the full thickness of the doubler, and then the cracks at sites 1 & 2 grow. Eventually, the crack at site 2 grows through the full shell thickness and becomes unstable.

Model-7h is a variation on model-7 (round blunted notch in doubler). Model-7h has a sharp, triangular notch cut along the longitudinal axis of the doubler. The pressure that initiates crack growth (site-1) is 1109 psi. There is no clear indication why the initial crack growth occurs at site-1 in model-7h, compared to the initial crack growth occurring at both site-1 and site-2 in model-7 (the round blunted notch configuration).

Model-8e is similar to model-7d, except that the fracture energy release rate in the doubler longitudinal weld (partial penetration) is 504 lb/in instead of the "derated" 400 lb/in used in model-7d. This increases the pressure that initiates crack growth from 674 psi in model-7d to 718 psi in model-8e.

Appendix D

Results Summary (cont.)

Progression of crack growth – crack surfaces projected onto finite element mesh

