

Case Study

U.S. CHEMICAL SAFETY AND HAZARD INVESTIGATION BOARD



OIL REFINERY FIRE AND EXPLOSION

No. 2004-08-I-NM
October 2005

Introduction

This case study describes the sudden release of flammable liquid and subsequent fire and explosion that occurred on April 8, 2004 at the Giant Industries' Ciniza oil refinery, Jamestown, NM. The incident injured six employees and caused evacuation of non-essential employees as well as customers of a nearby travel center and truck stop. Refinery equipment and support structures were damaged. Production at the unit was not resumed until the fourth quarter of 2004, and damage to the unit was in excess of \$13 million. Because of the serious nature of the incident—injuries to employees and extensive damages to facilities—the U.S. Chemical Safety and Hazard Investigation Board (CSB) produced this Case Study to share lessons learned so that similar occurrences might be prevented.

GIANT INDUSTRIES' CINIZA OIL REFINERY

Jamestown, NM

April 8, 2004

INSIDE . . .

| | |
|----------------------------|----|
| Process Description | 2 |
| Pre-Incident Events | 2 |
| Incident Description | 3 |
| Analysis of Incident | 6 |
| Lessons Learned | 11 |
| References | 12 |

1.0 Giant Operations

The parent company, Giant Industries Arizona, Inc., which is headquartered in Scottsdale, AZ, owns and operates the Ciniza refinery in Jamestown, NM. Subsidiaries of Giant Industries Inc. own and operate refineries in Bloomfield, NM and Yorktown, VA.

2.0 Refinery Operations

The Giant Ciniza refinery is located 17 miles east of Gallup, NM, and processes up to 22,000 barrels of crude oil per day. The refinery was purchased by Giant Industries in 1982.

Fortunately, no significant amount of HF was released in this incident.

3.0 Process Description

This incident occurred at the refinery's hydrofluoric acid (HF) alkylation unit. HF, a highly hazardous, toxic, and corrosive chemical, is used as a catalyst in the alkylation process. Fortunately, no significant amount of HF was released in this incident.

In HF alkylation, olefin and isobutane feedstocks are combined, then mixed with HF in a reactor vessel, where the alkylate¹ forms. (American Petroleum Institute 1999)

4.0 Pre-Incident Events

The day before the incident, alkylation unit operators attempted a regularly scheduled switch of the alkylate recirculation pumps in the Iso-Stripper unit. The primary electric pump would be taken out of service and the spare steam-driven pump started up. The switch was scheduled because of re-

curing problems with the spare pump's mechanical seal² leaking. This was done to free the spare pump's mechanical seal of any material that might cause it to function improperly. While attempting to put the spare pump in service, operators found it would not rotate.

Interviews with several operators revealed that some operators used the valve wrench's position . . . to determine whether the valve was open or closed, while others referred to the position indicator . . .

CSB Case Studies summarize incident investigation data and present conclusions based on CSB analyses. They do not discuss root and contributing causes or make safety recommendations—unlike the more comprehensive CSB Investigation Reports.



U.S. Chemical Safety and
Hazard Investigation
Board
Office of Investigations and
Safety Programs
2175 K Street NW
Suite 400
Washington, DC 20037-1848
202-261-7600
www.csb.gov

¹ Alkylate is a highly flammable gasoline blending component used to boost the octane of gasoline. It forms explosive vapor/air mixtures at above-ambient temperatures.

² Mechanical seals are used to keep the contents of rotating equipment such as pumps and compressors from escaping. They do this by sealing the shaft that protrudes from the casing.

5.0 Incident Description

The next morning, the maintenance supervisor assigned a mechanic specialist and a mechanic to repair the seal on the spare pump. An operator prepared a work permit that outlined the work to be done and the safeguards required for a safe repair.³ The valve used to isolate the pump for maintenance was a ¼ turn plug valve. A plug valve is used primarily for on/off, and some throttling services. It controls flow by means of a cylindrical or tapered plug with a hole in the center that lines up with the flow path of the valve to permit flow. The valve is opened or closed with the use of a valve wrench. A quarter turn of the valve blocks the flow path.

In preparing the pump for maintenance, the operator relied on the valve wrench to determine that the suction valve was open. He moved the wrench to what he believed was

³The work permit is issued by the operator and contains information on hazards involved in the maintenance operation, the appropriate personal protective equipment to be worn, and lock-out-tag-out (LOTO) information. Lockout/tagout refers to a program to control hazardous energy during the servicing and maintenance of machinery and equipment. Lockout refers to the placement of a locking mechanism on an energy-isolating device, such as a valve, so that the equipment cannot be operated until the mechanism is removed. Tagout refers to the secure placement of a tag on an energy-isolating device to indicate that the equipment cannot be operated until the tag is removed.

the closed position with the wrench perpendicular to the flow of product. Interviews with several operators revealed that some operators used the valve wrench's position relative to the flow to determine whether the valve was open or closed, while others referred to the position indicator on the valve stem. The valve was actually open.

The pump needed to be disassembled and the rear pump housing assembly and impeller moved to the shop for repair. Before leaving the area to obtain materials needed to remove the pump, the mechanic noticed that the valve position indicator on the suction valve body showed that the valve was open (See Figure 1). He did not relate this information to his co-workers.

Figure 1.

Suction Valve and Position Indicator as Found After Incident




Figure 2

Depressurizing Hose





Figure 3.

Damage to Area of Pump



The plant operator placed tags and locks on the suction and discharge valves to prevent inadvertent opening and to indicate that the valves had been closed. The mechanic specialist then placed tags and locks on the suction and discharge valves. When the mechanic returned, the mechanic specialist told him that the valves had been closed, secured, tagged, and locked per the facility's LOTO procedure and that they could remove the pump.

Neither mechanic observed the operator closing the valve. Both mechanics believed the task had been completed because the wrench used to open and close the valve was positioned perpendicular to the flow, and the operator had affixed his tags. (See Figure 1)

The operator then disconnected the pump's vent hose to verify that no pressure was in the pump case. The low point drain plug was not used because it was not equipped with a valve to isolate it from the line used for depressurizing the pump. (See Figure 2) Giant lockout/tagout procedures outlining operator responsibilities state:

On mechanical, pneumatic, steam and hydraulic equipment such as steam turbines, air pumps etc. this will include locking out of the energy isolating devices (i.e. valves) and verifying total release of any stored or residual energy by opening bleeders and verifying complete depressurization.

After uncoupling the hose at the connection to the flare line, a stream of alkylate flowed from the pump housing through the hose and subsided after a few seconds. The operator and the maintenance mechanics believed the pump had been de-pressured and was ready for removal. Actually, the vent line was plugged, and the pump was not de-pressured.

The pump shaft coupling and the flange connecting the pump to the pump case were unbolted. (See Figure 3) As the pump case flange was separated, alkylate was suddenly released at about 150 pounds per square inch gauge (psig) and 350 degrees Fahrenheit. The release produced a loud roaring sound that could be heard throughout the refinery.

The mechanic was blown over an adjacent pump and suffered broken ribs. Material was blown into the mechanic specialist's eyes so he made his way to an eyewash station, cleared his eyes, and then quickly exited the unit. Alkylate, which covered the plant operator's clothing, quickly ignited, seriously burning the operator in the ensuing fire. About 30 to 45 seconds after the initial release, the first of several explosions occurred.

The refinery's safety officer was about 150 yards away when the release occurred. In an attempt to turn on a fire monitor to suppress escaping vapors, the officer advanced towards the release. He was caught in the fire and injured. Two other workers suffered slight injuries escaping the area.

6.0 Analysis of Incident

6.1 Mechanical Integrity

A review of repair work prior to the incident revealed a history of repeated pump failures. The primary, electric, and steam-driven spare isostripper recirculation pumps had 23 work orders submitted for repair of seal-related problems or pump seizures in the one-year period prior to the incident (See Table 1).

Giant's mechanical integrity program did not effectively prevent these repeated failures of the pump seals. After the incident occurred, plugging material was found in the pump discharge line, the depressurizing line, pump housing, and the impeller. (See Figure 4). Giant's approach to these frequent pump seal problems was an example of breakdown maintenance. In other words, pump failures were addressed when the equipment finally broke down, instead of identifying causes of breakdowns and preventing them before they occurred again.

The Center for Chemical Process Safety (CCPS) recommends that maintenance programs troubleshoot and search for possible hidden or multiple reasons for frequently occurring problems. (CCPS, *Guidelines for Safe Process Operations and Maintenance* 1995). An effective mechanical integrity program

The primary, electric, and steam-driven spare isostripper recirculation pumps had 23 work orders submitted for repair of seal-related problems or pump seizures. . .

Table 1**Seal-Related Repair Work for Isostripper Recycle Pumps**

| DATE | PUMP | PROBLEM |
|------------------------|--------------|-------------------------|
| 1. April 17, 2003 | P-5A (Elec.) | Seal leak |
| 2. May 9, 2003 | P-5B (Stm.) | Pump spraying from seal |
| 3. May 23, 2003 | P-5A (Elec.) | Repair seal |
| 4. June 9, 2003 | P-5B (Stm.) | Repair seal |
| 5. June 9, 2003 | P-5A (Elec.) | Repair seal |
| 6. June 18, 2003 | P-5A (Elec.) | Repair seal |
| 7. June 20, 2003 | P-5A (Elec.) | Replaced seal |
| 8. July 31, 2003 | P-5A (Elec.) | Replaced seal |
| 9. August 22, 2003 | P-5B (Stm.) | Seal leak |
| 10. August 25, 2003 | P-5B (Stm.) | Replaced seal |
| 11. September 26, 2003 | P-5B (Stm.) | Replaced seal |
| 12. September 26, 2003 | P-5A (Elec.) | Replaced seal |
| 13. October 14, 2003 | P-5A (Elec.) | Seal leak |
| 14. December 6, 2003 | P-5A (Elec.) | Replaced seal |
| 15. December 9, 2003 | P-5B (Stm.) | Seal leak |
| 16. December 9, 2003 | P-5A (Elec.) | Seal leak |
| 17. December 15, 2003 | P-5B (Stm.) | Replaced seal |
| 18. December 15, 2003 | P-5A (Elec.) | Seal leak |
| 19. January 28, 2004 | P-5A (Elec.) | Seal leak |
| 20. March 22, 2004 | P-5A (Elec.) | Seal leak |
| 21. April 1, 2004 | P-5A (Elec.) | Pump seal leaking |
| 22. April 3, 2004 | P-5A (Elec.) | Pump seal leaking |
| 23. April 7, 2004 | P-5A (Elec.) | Repair pump seal |

would have investigated and resolved the problems that were repeatedly causing the recirculation pump seals to fail.

6.2 Corrosion and Scale Formation

At Giant, the isostripper pumps frequently had plugging problems.

A number of factors contribute to the formation of corrosion, scale, and deposits, which in turn can lead to the fouling or scoring of pump seals. The failure of the seals is not typically caused by corrosion of the seal faces, but by the scoring/erosion (galling) of the seal faces from a solid fouling material. Carbon seal faces such as those used for the pump involved in this incident, are prone to contaminant scoring.

Some corrosion and scale products occur because of operating temperatures and pressures at which an HF alkylation unit is run. Many HF alkylation units operate at 125 psig or lower. The isostripper column at the Giant refinery is normally operated at about 150 psig. Operation at higher pressures requires much higher temperatures, which can result in accelerated corrosion of equipment.

Plugging and fouling material can also occur as soft iron fluoride scale develops and forms in the tower overhead and domes when preparing to shut down the unit for

cleanup activities. Some of this soft, water-laden scale comes off when the unit is running. The rest creates a site for extremely fast and extensive corrosion, resulting in a large amount of scale being added into the process. Scale may accumulate and settle at low points and orifices in equipment such as spare pumps.

Giant management did not investigate why excessive iron fluoride generation in the process caused the mechanical seals on the alkylate recirculation pumps to fail repeatedly.

6.3 Valve Design

Examination of the 6-inch, $\frac{1}{4}$ turn, plug valve after the incident determined that it was originally designed to be opened and closed by a gear-operated actuator. The gear-driver had been removed and was replaced by a valve wrench. The wrench was a two-foot-long bar inserted into a collar. Because it had a square shape, the collar could be easily removed and repositioned on the valve stem in different directions. (See Figure 5)

Giant did not consider the design or engineering safety implications of changing from a gear-operated valve actuator to using a wrench as a valve handle.

Interviews with operators revealed they would sometimes determine

Figure 4

Plugging Material Found in Discharge Valve




Figure 5

Spare Pump Valve Wrench Collar



Figure 6

Plug Valve in the Open Position



Both the plant operator who attached the locks and the mechanics who removed the pump mistakenly believed the suction valve had been closed



whether the valve was open or closed by the valve wrench position. If the wrench was perpendicular to flow through the valve, it was considered closed. If the wrench was aligned parallel to the flow, the valve was thought to be open.

In some instances, set screws would be loosened, and the wrench would be removed and placed on the pump base to provide better clearance for personnel walking nearby. When the valve was to be opened or closed, the wrench would be replaced on the valve stem. In the Ciniza oil refinery incident, the valve wrench collar was installed in the wrong position.

Figure 6 is a drawing of the plug valve in the open position with the wrench in the perpendicular or perceived “closed” position.

Both the plant operator who attached the locks and the mechanics who removed the pump mistakenly believed the suction valve had been closed, in part because the valve wrench was perpendicular to the normal pipe flow. After he returned from obtaining materials needed for pump removal, the mechanic who earlier observed the position indicator in the open position began working on the opposite side of the pump, so he did not realize the valve position indicator still indicated the valve was open. From his vantage point, he observed the valve wrench in a perpendicular orientation and believed the valve was closed.

Technically, the wrench was not intended to indicate valve position because the valve was equipped with the position indicator, which was located on the valve stem. (See Figure 7) In practice, however, some plant employees used the wrench to determine valve position, partly because the wrench was much more visible than the actual valve position indicator.

6.4 Human Factors Consideration


Donald A. Norman (*The Design of Everyday Things*) states that design of a system's controls, as seen by the operator, must accurately reflect the actual state of the system, and that movement of the controls must operate the system in the manner the operator would naturally expect from the visual cues. He says that:

Natural mappings are the basis of what has been called "response compatibility" within the field of human factors and ergonomics. The major requirement of response compatibility is that the spatial relationship between the positioning of controls and the system or objects upon which they operate should be as direct as possible, with the controls either on the objects themselves or arranged to have an analogical relationship

to them. In similar fashion, the movement of the controls should be similar or analogous to the expected operation of the system. Difficulties arise wherever the positioning and movements of the controls deviate from strict proximity, mimicry or analogy to the things being controlled.

Figure 7

Suction Valve & Position Indicator



. . . [T]he wrench was much more visible than the actual valve position indicator

◆ Giant’s use of the wrench instead of the original valve actuator was a significant equipment change and should have been included in the company’s MOC program.

6.5 Management of Change

OSHA’s Process Safety Management standard (1910.119) states that any change that may affect a process covered by that standard should trigger a management of change (MOC) analysis. The only exception to this is when the change is a “replacement in kind.”⁴

In some instances, the smallest of changes can lead to a significantly unexpected outcome. In *Still Going Wrong*, safety expert, Trevor Kletz cites an example in which the central bolt on a three-way valve was marked by operators to indicate the position of the valve. This was reportedly done because the original markings on the valve itself were hard to see. The marks corresponded to the valve position.

Two washers were placed under the bolt in subsequent maintenance, and the valve could no longer be screwed all the way in to close it. The marks on the central bolt no longer corresponded with the actual valve position. However, operators set the valve according to marks on the bolt, resulting in a misdirection of flow and a subsequent explosion.

Giant’s use of the wrench instead of the original valve actuator was a

significant equipment change and should have been included in the company’s MOC program.

6.6 Lockout/Tagout and Isolation

While the Giant mechanics and operator locked and tagged the pump involved in this incident, they mistakenly believed the pump had been isolated and depressured. They had not adequately verified that the pump was isolated or drained before locking and tagging it out. Effective LOTO procedures include specific requirements for testing machines to determine and verify the effectiveness of lockout devices, tagout devices, and other energy-control measures. (OSHA, 2002)

⁴“Replacement in Kind” means replacement that satisfies the design specification

7.0 Lessons Learned

7.1 Valve Modification

Any valve position indication used by employees to determine the open/closed position of valves should communicate accurate information to employees. Valve modification should receive MOC analysis to determine whether new hazards or risks have been introduced.

Although the valve had a position indicator, employee practice was to sometimes use the position of the valve wrench to determine the open/closed status of the valve. The valve collar and wrench were not permanently fixed to the stem and were positioned incorrectly. When the valve was changed from a wheel and gear-driven mechanism to a wrench, the collar could be attached in the wrong position. An MOC hazard analysis was not conducted. If an MOC had been used, it could have revealed the potential for the valve wrench to be oriented in the wrong direction.

7.2 Lockout/Tagout

Lockout/tagout programs should require effective verification that equipment has been isolated, depressurized and drained.

Although Giant employees believed the pump was isolated before it was

locked out, the facility lacked procedures to verify that the pump had been isolated, depressurized and drained. Equipment being prepared for maintenance should be drained of all liquid at a low point drain.

7.3 Mechanical Integrity

Mechanical integrity programs should prevent breakdown maintenance. Identifying operating conditions that could be contributing to equipment failure is a critical component of mechanical integrity.

Instead of determining the cause of frequent pump malfunctions and then implementing a program that would prevent problems before they occurred, Giant used breakdown maintenance by making repeated repairs to the pump seals after failure.

The valve collar and wrench were not permanently fixed to the stem and were positioned incorrectly.

Instead of determining the cause of frequent pump malfunctions and then implementing a program that would prevent problems before they occurred, Giant used breakdown maintenance . . .

8.0 References

American Petroleum Institute

1999. *The Use of Hydrofluoric Acid in the Petroleum Refining Alkylation Process*, Refining Department Background Paper, April 1999

Center for Chemical Process Safety, *Guidelines for Safe Process Operations and Maintenance*, 1995

Giant, *Standard Safety Regulations*.

Kletz, Trevor, *Still Going Wrong*, 2003

Norman, Donald A., *The Design of Everyday Things*, 1990

Occupational Safety and Health Administration (OSHA), *Process Management Standard*.

OSHA, *Control of Hazardous Energy Lockout/Tagout*, OSHA 3120, 2002



**U.S. Chemical Safety and
Hazard Investigation
Board**
2175 K Street NW,
Suite 400
Washington, DC 20037-
1848
(202) 261-7600



CSB is an independent Federal agency whose mission is to ensure the safety of workers, the public, and the environment by investigating and preventing chemical incidents. CSB is a scientific investigative organization; it is not an enforcement or regulatory body. Established by the Clean Air Act Amendments of 1990, CSB is responsible for determining the root and contributing causes of accidents, issuing safety recommendations, studying chemical safety issues, and evaluating the effectiveness of other government agencies involved in chemical safety.

No part of the conclusions, findings, or recommendations of CSB relating to any chemical incident may be admitted as evidence or used in any action or suit for damages arising out of any matter mentioned in an investigation report (see 42 U.S.C. § 7412(r)(6)(G)). CSB makes public its actions and decisions through investigation reports, summary reports, safety bulletins, safety recommendations, case studies, incident digests, special technical publications, and statistical reviews. More information about CSB may be found at www.csb.gov.