

## **Kuraray Investigation – Factual Update**

Kuraray America EVAL Facility, Pasadena TX Fire, May 19, 2018

Steve Cutchen October 24, 2018

#### U.S. Chemical Safety and Hazard Investigation Board Kuraray America EVAL Facility, Pasadena TX

## Fire, May 19, 2018

# Ethylene and Vinyl ALcohol $(CH_2-CH_2)_m - (CH_2-CH)_n -$



EVAL<sup>™</sup> is the Kuraray trademark for a plastic made from ethylene and vinyl alcohol.

**EVAL's primary property is as a barrier** 


EVAL blocks oxygen, and is used as a packaging material for foods


EVAL blocks other gases as well. It is used in plastic storage containers and in the plastic automobile fuel tanks.

Manufacturing facilities: Japan Belgium Texas























































U.S. Chemical Safety and Hazard Investigation Board

#### **Sequence of Events**

Wednesday, May 16 10:30 Refrigerant opened to Reactor Coolers.

Friday, May 18 15:00 Reactor Pressure Test begins using ethylene gas.

Friday, May 18 23:20 Ethylene begins condensing. Reactor begins cooling. Reactor pressure still being raised.

Saturday, May 19 07:00 Low Reactor temperature noticed. Refrigerant blocked, Reactor heated. Reactor pressure rising.

Saturday, May 19 10:28 Reactor overpressures. Reactor vapor ejected horizontally from relief valve. Vapor ignited by welding machine – Fire Marshal.




#### Kuraray America EVAL Facility, Pasadena TX Fire, May 19, 2018



Credit: Houston Chronicle



#### Kuraray America EVAL Facility, Pasadena TX Fire, May 19, 2018



Credit: Tiffany Craig, KHOU TV, courtesy of Edward Ross

Initially a Flash Fire, flames propagated back to relief valve, becoming a Jet Fire.

Fire burned for almost three minutes, until relief valve closed.

U.S. Chemical Safety and

Hazard Investig


Contract workers in the vicinity were performing activities including welding, insulating, and painting. They immediately evacuated when the fire erupted.

Workers suffered burns, or were injured by jumping from heights, or falling while running to escape the fire.

Twenty-one injured workers were transported to medical facilities for treatment.

One contract worker remained in critical condition for several days from life-threatening burns.











The CSB investigation is ongoing.

Investigators continue to collect data and evidence from the site.

Investigators will conduct an analysis of this incident based upon evidence collected during the course of the investigation.

A final report, including facts, analysis, conclusions, and recommendations will be issued at the conclusion of the investigation.

This PowerPoint presentation is not a stand-alone document.

It is meant as a visual accompaniment to an oral update of the May 19, 2018 fire at the Kuraray EVAL facility in Pasadena, TX.

It does not supplant the actual investigation analysis which will be located at https://www.csb.gov/kuraray-america/