

**Chemical Safety and Hazard Investigation Board** 

OFFICE OF GENERAL COUNSEL

#### Memorandum

To: Board Members

From: Chris Lyon Chris Lyon Acting General Counsel

Cc: Amanda Johnson, Recommendations Specialist Leadership Team

Subject: <u>Board Action Report</u> – Notation Item 2024-28

Date: December 21, 2023

On December 20, 2023, the Board approved Notation Item 2024-28, thereby designating Recommendation 2018-03-I-TX-R5, to Kuraray America, Inc. (from the Kuraray Pasadena Release and Fire investigation (2018-03-I-TX)), with the status of Open – Acceptable Response or Alternate Response.

# **Voting Summary – Notation Item 2024-28**

**Disposition: APPROVED** 

Disposition date: December 20, 2023

	Approve	Disapprove	Calendar	Not Participating	Date
S. Johnson	X				12/20/2023
S. Owens	X				12/20/2023
C. Sandoval	X				12/20/2023



# U. S. Chemical Safety and Hazard Investigation Board RECOMMENDATION STATUS CHANGE SUMMARY

Report:	Kuraray Pasadena Release and Fire	
<b>Recommendation Number:</b>	2018-03-I-TX-R5	
Date Issued:	December 21, 2022	
Recipient:	Kuraray America, Inc.	
New Status:	Open – Acceptable Response or Alternate Response	
Date of Status Change:	December 20, 2023	

# **Recommendation Text:**

Review the Center for Chemical Process Safety guidance on recognizing catastrophic incident warning signs and then develop and implement a program for the EVAL Plant that incorporates warning signs into its safety management system.

# **Board Status Change Decision:**

### A. Rationale for Recommendation

On the morning of May 19, 2018, the pressure relief devices of a reactor used to make ethylene and vinyl alcohol copolymer (EVAL) activated and discharged ethylene into the air through horizontally oriented discharge piping. The resulting flammable vapor cloud found a heat source and ignited. The fire burned for approximately three minutes until enough ethylene was released to reduce the pressure inside the reactor to allow the pressure relief valve to close. Kuraray American, Inc. (Kuraray) reported releasing 2,347 pounds of ethylene. Several workers sustained injuries resulting from the fire as well as from trying to escape the fire. Twenty-one injured workers were transported to off-site medical facilities for treatment. Additionally, two workers were life-flighted from the Kuraray facility.

The U.S. Chemical Safety and Hazard Investigation Board (CSB) investigated the incident and found several safety issues including failures in pressure-relief system discharge design, excluding non-essential personal during transient operations, and weakly implemented process safety management system elements. As a result of these findings, the CSB issued twelve recommendations to Kuraray. This status change summary addresses CSB Recommendation No. 2018-03-I-TX-R5.

### B. Response to the Recommendation

Kuraray notified the CSB that the company has implemented a program to assist technicians in recognizing various levels of warnings, including catastrophic incident warning signs. The EVAL site has also performed an initial warnings signs survey as a method to integrate warning sign concepts into the site process safety management systems. Once this survey is completed, the CSB can evaluate this recommendation for closure.

# C. Board Analysis and Decision

Based upon the information above, the Board voted to change CSB Recommendation No. 2018-03-I-TX-R5 to: "Open – Acceptable Response or Alternate Response."